

Technical Note: NAVTRAEQUIPCEN IN-50

TRAINING CONSIDERATIONS IN SUPPORT OF REFURBISHMENT OF DEVICE 2569D FOR THE NAVAL RESERVE

Leonard Ryan, John Smith, and Diane Planert Plans, Program and Analysis Department Naval Training Equipment Center Orlando, Florida 32813

FINAL REPORT

June 1979



DoD Distribution Statement

Approved for public release; distribution unlimited.



PRAZEKTEG CONSTRUCTIONS IN SUPPORT OF REPUREISHEDRY OF DEVICE 2F630 FOR THE NAVAL DESERVE

Leonard Ryan, John Smith, and Diane Planert plans, Program and Analysis Department Naval Training Equipment Center Orlando, Plorida 32813

June 1979

COVERNMENT RICENS IN DAVA STATEMENT

Reproduction of this publication in whole or in part is permitted for any purpose of the United States Government.

rector

one, Program and Analysis Department

SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

REPORT DOCUMENTATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM
NAVTRAEQUIPCEN TN-60	. 3. RECIPIENT'S CATALOG NUMBER
TITLE (and Subtitio)	S. TYPE OF REPORT A PERIOD COVERED
TRAINING CONSIDERATIONS IN SUPPORT OF REFURBISHMENT OF DEVICE 2F690 FOR THE	Final Report
NAVAL RESERVE	
ACTRON(I)	8. CONTRACT OR GRANT NUMBER(a)
Leonard E. /Ryan, John/Smith/	e legal/teed
PERFORMING ORGANIZATION NAME AND ADDRESS Plans, Programs and Analysis Dept (N-82) Naval Training Equipment Center Orlando, FL 32813	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS NAVTRAEQUIPCEN Task No WA4130PI
. CONTROLLING OFFICE NAME AND ADDRESS	P. PEROPT DATE
[11]	Jun 79
THE RESERVE ALPOHOUSE COMPANY OF THE CO.	48
MONITORING AGENCY NAME A AGORGODIA SHOWN LOS Controlling Office)	15. SECURITY CLASS. (of this report)
(12)51p.	Unclassified
	15a. DECLASSIFICATION/DOWNGRADING
DISTRIBUTION STATEMENT (of this Report)	
DISTRIBUTION STATEMENT (of the obstract entered in Block 20, 11 different to	
SUPPLEMENTARY OTES	
. KEY WORDS (Continue on reverse side if necessary and identify by block number	
P-3 aircraft training Device 2F6 OFTs Device 2F8	
	substitution
. ABSTRACT (Continue on reverse side if necessary and identify by block number,	,
This report was prepared in response to initiate a study covering various possishing Device 2F69D which is scheduled Naval Reserve at NAS Willow Grove, Penns	e to a NAVAIRSYSCOM task sible degrees of refur-for transfer to the ylvania.
Specific objectives of the study we	re to determine: the

DD 1 JAN 79 1473 A EDITION OF 1 NOV 65 IS OBSOLETE 5/N 0102-LF-014-6601

Unclassified

SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

390 462

Du


20. ABSTRACT (continued)

- . the overall NAVRES/NAVRESASWTAC P-3 A/B training pipeline;
- . specific pilot, copilot, and flight engineer training requirements;
- . —functional systems of the 2F69D OFT required to support identified training requirements;
- . refurbishment/overhaul priority considerations of 2F69D OFT functional systems based on their overall contribution to training
- . Calternative methods/media to support the NAVRES training program; e.g., cockpit procedure trainer and/or Device 2F87F (P-3 OFT); and
- . 2F69D maintenance and logistic personnel support
 requirements.

The recommendation in this report is to transfer Device 2F69D OFT from Brunswick, Maine, in an as is condition, and initiate procurement of a new Device 2F87F. Cost savings based on flight hour reductions are discussed.

TABLE OF CONTENTS

Section			a				P	age
1 '	INTRODUCTION		٠					5
	Purpose		:	:	• ,	:		5
II	RESASWTAC TRAINING PROGRAM		•					8
<u>a</u>	Mission							8
III	FUNCTIONAL SIMULATION REQUIREMENTS							
	Simulation Requirements for Pilot, Cope and Flight Engineer				:			12 20
IV	REFURBISHMENT PRIORITIES AND SUPPORT P	ERS	ONI	NEI	٠.			24
	Refurbishment Priorities		*	:	:		•	24 25
V	TRAINING DEVICE ALTERNATIVES AND RECOM	MEN	DA'	ric	N	•	•	27
	Training Device Alternatives Recommendation Based on Training		•		•		•	27
	Considerations		•	•	•	•	•	30
VI	AN IMPORTANT COST FACTOR							32
APPENDIX	A Patrol Squadron/Unit Syllabus for Of 3, and 4					•		39
APPENDIX	B Patrol Squadron/Unit Syllabus for O	FT	5.					45
APPENDIX	C Patrol Squadron/Unit Syllabus for I	UT	OF	r 1	١.			47



LIST OF ILLUSTRATIONS

Figure				Page
1	Cost Savings vs. Flight Hour Reduction	•		36
	A STATE OF THE STA			
	MCSO-de Massacrata Describer de la compansacrata de la compansacra			
	LIST OF TABLES			
Table	Planged Othligation of 20000 0000			Page
d 1	Planned Annual OFT Utilization			11
2	Equipment References for Training Tasks			13
3	Alternative Media Capability and Cost Factors			28
1 4	Cost Savings Through Use of Device 2F69D for NATOPS and Instrument Checks			34

ACKNOWLEDGMENTS

The collection of information presented in this report was greatly facilitated by the cooperation and dedication of the Commander and training staff of the NAVRES ASWTAC school at NAS Willow Grove. Their support of the requirements survey was invaluable to preparation of this report.

Appreciation is owed to James J. Riley of the NAVTRAEQUIPCEN for his technical assistance and storehouse of knowledge regarding the history of Device 2F69D. Dr. William M. Swope, Paul G. Scott, and Robert F. Browning of the Training Analysis and Evaluation Group provided valuable inputs regarding cost data, and William T. Harris of the NAVTRAEQUIPCEN contributed much time sorting out functional simulation requirements.

SUMMARY

This report was prepared in response to a NAVAIRSYSCOM task to initiate a study covering various possible degrees of refurbishing Device 2F69D which is scheduled for transfer to the Naval Reserve at NAS Willow Grove, Pennsylvania.

The study team visited the RESASWTAC school at NAS Willow Grove and was briefed on the training program of RESASWTAC and the Reserve squadrons. Training tasks based on the existing squadron syllabus were used as a basis for RESASWTAC training tasks. These tasks were compared with NATOPS normal and emergency procedures to determine the aircraft equipment involved in each task. This process provided a list of OFT equipment necessary to train the tasks.

Based on the training tasks and the training device requirements, alternative media and associated cost factors were investigated. Consideration was given to the following: (1) Convert 2F69D to a CPT-level device, (2) transfer the 2F69D "as is" and attempt improved maintenance/logistics support, (3) overhaul/refurbish required existing components (without digital upgrade), (4) overhaul/refurbish required existing components and digitally upgrade the NAVAIDS capability, and (5) procure a new digital 2F87F. The recommended option from the five alternatives considered was to combine alternatives (2) and (5); i.e., transfer the Brunswick 2F69D to Willow Grove "as is" and procure a device 2F87F for follow-on training.

Cost savings based on flight hour reductions are also discussed.

SECTION I

INTRODUCTION

In the 1st quarter FY 80, the P-3 A/B OFT, Device 2F69D, currently located at NAS Brunswick, Maine, is scheduled to be transferred to RESASWTAC, NAS Willow Grove, Pennsylvania. The tactics portion of the 2F69D will be modified to reflect updated operational equipment and will be transferred to RESASWTAC during the 2nd quarter FY 80. RESASWTAC expects to use the 2F69D WST for training purposes through the 1980s.

The 2F69D OFT has been in use approximately 13 years and has never undergone a comprehensive refurbishment. In its present condition, the device provides unrealistic flight characteristics and has numerous maintenance problems. The Chief of Naval Reserve (CNAVRES) has expressed concern about the condition of the device and also about logistics/supply support problems associated with the device. These problems were addressed recently in a meeting of the P-3 Integrated Logistics Support Team (ILSMT). The minutes of the ILSMT meeting state that "Unless a general update/refurbishment of the OFT is conducted upon transfer to the Reserves, the OFT will not be maintainable and hence of little training value."

To resolve these problems, NAVAIRSYSCOM has tasked NAVTRAEQUIP-CEN to initiate a study covering various possible degrees of refurbishment and the associated cost.

PURPOSE

The purpose of this report, in conjunction with engineering cost and logistics data to be provided separately by Code N-412,

is to provide the NAVTRAEQUIPCEN Project Director with information needed to determine the extent to which 2F69D OFT refurbishment/ overhaul is required and justified in terms of NAVRES P-3 A/B training requirements and available resources. Specific objectives of the study were to determine the following:

- . the overall NAVRES/NAVRESASWTAC P-3 A/B training pipeline
- specific pilot, copilot, and flight engineer training requirements
- functional systems of the 2F69D OFT required to support identified training requirements
- refurbishment/overhaul priority considerations of 2F69D OFT functional systems based on their overall contribution to training
- alternative methods/media to support the NAVRES training program; e.g., cockpit procedure trainer and/or Device 2F87F (P-3 OFT)
- . 2F69D maintenance and logistic personnel support requirements.

METHOD

NAVRES P-3 A/B OFT training requirements data were obtained from experienced instructor pilot and flight engineer personnel during a 4-day visit to the RESASWTAC School located at NAS Willow Grove, Pennsylvania. At the time of the visit, a training curriculum had not been prepared and specific training objectives were not available; however, the school's instructor and NATOP's

personnel had previously developed plans for the use of the OFT and devoted four full days briefing the NAVTRAEQUIPCEN analysis team on their plans and requirements. The planned utilization corresponded closely to the present Reserve Force Squadron (RESFORON) squadron/unit OFT syllabus.

To ensure that all required pilot and flight engineer OFT capabilities were systematically analyzed and documented, the P-3 A/B NATOPS (NAVAIR 01-75PAA-1) was used as a basis for data collection. NATOPS presents all approved operating procedures for the pilot, copilot, and flight engineer. All flight controls and indicators, as well as their operation during normal and emergency ground and flight procedures, are specified.

Determination of 2F69D functional systems required to support training program goals was based on a comparison of NAVRES stated requirements with the systems, controls, and indicators shown by NATOPS to be involved.

During the process of identifying pilot and flight engineer OFT requirements, consideration was given to the possible existence and adequacy of alternate "hands-on" training capabilities or options so that requirements/capabilities were not specified where existing capabilities were adequate.

Conclusions about the extent of refurbishment are the province of the NAVTRAEQUIPCEN, NAVAIRSYSCOM, and CNAVRES and will involve cost factors associated with refurbishment and cost comparisons with alternative systems.

SECTION II

RESASWTAC TRAINING PROGRAM

MISSION

The RESASWTAC mission is to provide ASW training to all VP, VS, and HS reserve air activities. Specialized P-3 A/B training is provided to USNR, USN, and foreign flight crews and maintenance personnel. In addition to the basic mission, RESASWTAC provides celestial navigation training for all navigators, oceanography and basic ASW for all ASW activities, and communication operator training for VR squadrons.

TRAINEES

A typical training load during a 1-year period is listed below:

- . ACDUTRA involving 255 pilots and 170 flight engineers who will report to NAS Willow Grove 1 week each year
- . Transition training for 48 non-P-3 pilots
- . Weekend pilot and flight engineer proficiency training involving 864 pilots and flight engineers
- . Instructor-Under-Training (IUT) involving 50 pilots
- . Squadron Augment Unit (SAU) training involving 91 pilots
- Advanced second mechanic training involving 32 flight engineers

Because of the distance of some NAVRES squadrons from RESASWTAC, all pilots will not have access to the OFT.

- . Second mechanic initial training involving 32 flight engineers
- . Systems review training involving 24 flight engineers
- . NATOPS checks involving 75 pilots and 30 flight engineers
- Transition training involving 28 former P-3C pilots.

PLANNED UTILIZATION OF 2F69D OFT

The present RESFORON flight hour allowance is 120/pilot/year.

The minimum number of flight hours, as established by CNO, is

100/pilot/year.

Though OPNAVINST 3710.7J states that up to 50 percent of required annual flying time can be performed in a 2F69D type device, pilot flight currency requirements specify that 45 hours of flying time each 6 months, or 90 hours each year, must be performed in the aircraft. Thus, it would be possible for a NAVRES pilot to substitute up to 30 hours of his annually funded 120 hours of flying time in an approved OFT such as the 2F69D. RESASWTAC intends to take advantage of simulator substitution and conduct 60 to 65 percent of the NATOPS check and the entire instrument check in the OFT. OFT use in lieu of the aircraft will provide for a more beneficial use of funded aircraft flying hours (such as additional full crew operational/training missions).

In addition to training conducted by RESASWTAC, the RESFORONS also have requirements for training in the OFT. The Patrol Squadron/Unit Training Manual (CNAVRESINST 3500.2A) specifies the following OFT use in P-3 A/B pilot and instructor pilot qualification:

- Phase III initial qualification for third pilot requires satisfactory completion of OFT periods 1 4 (see appendix A)
- Phase III initial qualification syllabus for patrol plane commander requires that OFT training session 5 be used as the basis for Personnel Qualification Standards (PQS) criteria and qualification (see appendix B for OFT 5 tasks)
- . Instructor pilot (IP) qualification requires IUT OFT 1 (see appendix C).

Flight engineer OFT use is not specified in the instruction.

Planned annual OFT utilization hours are listed in table 1 along with user pipeline count and training period data. The data show that NAVRES plans heavy utilization of an OFT in support of their training program and aircrew evaluation requirements.

TABLE 1. PLANNED ANNUAL OFT UTILIZATION

Category of Use	User Count	OFT Periods/ Period Length	Hours of Utilization
ACDUTRA	255 P 170 FE	2/4 Hrs*	1,133
Non-P-3 Trans.	48 P	8/4 Hrs	768
Weekend Training	864 P/FE	4/4 Hrs*,**	768
IUT segreta seera	50 P	2-3/4 Hrs***	500
SAU	91 P	2/4 Hrs	364
Adv. 2nd Mechanic	32 FE	2/4 Hrs	256
Init. 2nd Mechanic	32 FE	2/4 Hrs	256
System Review	24 FE	2/4 Hrs	192
NATOPS Checks	75 P 30 FE	1/1.5 Hrs***	158
P-3C to P-3 A/B	28 P	2/4 Hrs	112
Instr. Checks	50 P	1/1.5 Hrs***	120

Total Hours of Utilization 4,627

^{*} A maximum of 28 weekends will be available for this training.
** Not all pilots will receive their OFT training at RESASWTAC.
***Pilot checks and instructor training will apply to one pilot per OFT period.

SECTION III

FUNCTIONAL SIMULATION REQUIREMENTS

SIMULATION REQUIREMENTS FOR PILOT, COPILOT, AND FLIGHT ENGINEER

Functional simulation requirements of the 2F69D and alternative devices are directly tied to training tasks required to train the various categories of users shown in table 1. The OFT training tasks involved are contained in the present Patrol Squadron/Unit OFT syllabus for the plane commander and third pilot (see appendices A, B, and C). The syllabus for third pilot OFT sessions 1 through 4 is organized on a "phase-of-flight" basis; i.e., each session begins with the before-start checklist and progresses through taxi-takeoff-climb-cruise-descent-landing and secure checklist. During each phase of flight, normal and emergency procedures are covered. OFT 5, pertaining to command pilot training, is concerned primarily with malfunctions.

All tasks trained in the OFT are covered in NATOPS which specifies the normal and emergency procedures for operating all systems, controls, and indicators involved in each task. Therefore, it is possible to refer to NATOPS to identify the aircraft system controls and indicators necessary to train each task. The OFT functional simulation required to adequately train the tasks will be those identified during this process.

Training tasks and the references which identify the equipment involved for the pilot, copilot, and flight engineer are shown in table 2. Associated NATOPS (NAVAIR 01-75 PAA-1) or other checklist references are included to provide engineering personnel

TABLE 2. EQUIPMENT REFERENCES FOR TRAINING TASKS

			REFERENCES	
TRAINING TASKS (NORMAL PROCEDURES)	NATOR 01-75 PA	Control of the Contro	NAVAIR 01-75PAC-6-1	MRC
Auxiliary Power Unit Procedures Inspection	hras (8) Grani		Items 23 & 24	
- Turnaround interior checks	Sec 3-2	& 3-3		
. APU or external power preoperational check				
. Flight station check				
- APU ground operation				
- Starting the APU				
- Stopping the APU				
Preflight Inspection	Sec 3-3			
- Auto feather checks				
- Auto feather system				Car
- Prop unfeather system				11
- Engine fire warning test				
Automatic Pilot and MM-4 Flag/Source Ground Check	Sec 3-4			
Before Starting Engines	Sec 3-5		e compression and the	
Starting Engines	Sec 3-5			
- Normal start (electrical system, including control	Sec 3-6			
panel, must operate)				
 Oil cooler flap switches and control panel must also operate 				
- Control of bleed air manifold pressure gauge is required				
- Stagnated and stalled start	Sec 3-8			
- Hot start	Sec 3-8			

TABLE 2. EQUIPMENT REFERENCES FOR TRAINING TASKS (continued)

		REFERENCES	
TRAINING TASKS (NORMAL PROCEDURES)	NATOPS 01-75 PAA-1	NAVAIR 01-75PAC-6-1	MRC
After Start (Item 4, MAD and Doppler power not required)	Sec 3-8		
Engine Ground Operation	Sec 3-8		
Aircraft Lights Operation (only dummy switches needed)	Sec 3-8		
Operational Checks	Sec 3-10		
- Fuel governor, pitch lock and reverse horsepower check (Systems must be operable)	Sec 3-10	go Emograu 1952, - - Saut Sini Start	
- Engine anti-ice check	Sec 3-11		
- Wing de-ice system check	Sec 3-11		
Takeoff (Item 1 condition V-set and item 17 harness-set not required)	Sec 3-12		
Takeoff Procedures	Sec 3-12		
- Normal takeoff	Sec 3-12		
- After takeoff climb	Sec 3-14		
Climb (Gauges, switches must be operable; dummy swithces for lights)	Sec 3-14		
In-flight NTS Check (NTS must operate)	Sec 3-15		
 Cruise (Autopilot must be operable; Radar altimeter not required) 	Sec 3-15		
 Engaging automatic pilot in flight (Radar altimeter not required) 			

TABLE 2. EQUIPMENT REFERENCES FOR TRAINING TASKS (continued)

REDUCATIVES	REFERENCES
TRAINING TASKS (NORMAL PROCEDURES)	NATOPS NAVAIR 01-75 PAA-1 01-75PAC-6-1 MRC
Two- and Three-Engine Loiter Procedures	Sec 3-17
 Two- and three-engine loiter shutdown procedure 	Sec 3-18
Crossfeed Procedure	Sec 3-18
Engine Restart During Flight (Restart)	Sec 3-18
Descent Procedures	Sec 3-20
Landing Procedures	Sec 3-20
 Approach (Item 2 set condi- tion V not required) 	Sec 3-20
- Landing	Sec 3-22
Wave-off	Sec 3-25
After Landing (Items 3 IFF-set not required)	Sec 3-25
Securing the Aircraft	Sec 3-25
Windmill Start Procedures	Sec 3-33
Instrument Approaches TRAINING TASKS (EMERGENCY PROCEDURES	Require: (1) GCA and one other landing and (TACAN, VOR, or ILS without glideslope) (2) Pilot and copilot speaker must be operative (3) UHF radio communication
General Emergency Procedures	Sec 5-1
- APU fire	Sec 5-1
- Fuselage fire or electrical fire of unknown origin	Sec 5-2

TABLE 2. EQUIPMENT REFERENCES FOR TRAINING TASKS (continued)

		REFERENCES	
TRAINING TASKS (EMERGENCY PROCEDURES)	NATOPS 01-75 PAA-1	NAVAIR 01-75PAC-6-1	MRC
Ground Emergencies	Sec 5-28	sea-serer bra -	owij.
- Engine fire on the ground	Sec 5-28	6976020	
Takeoff Emergencies	Sec 5-29		
- Engine failures	Sec 5-29		
. During takeoff	Sec 5-29		
. Prior to refusal speed	Sec 5-29		
. After reaching refusal speed	Sec 5-29		
Propeller Malfunctions	Sec 5-31		
 Propeller malfunctions below refusal speed (Must have cor- responding control "feel")* Propeller malfunction above 	Sec 5-31		
refusal speed (Must have cor- responding control "feel")*	Sec 5-31		
In-flight Emergencies	Sec 5-33		
- Automatic pilot disconnect	Sec 5-33		
- Electrical system failures	Sec 5-33		
. Generator failure	Sec 5-33		
. Operation with one AC generator (Load monitoring of circuit is required)	Sec 5-33		
. Use of APU in flight	Sec 5-34		
. APU in-flight start procedures	Sec 5-34		
. APU in-flight with altitud automatic load monitoring	e Sec 5-34		

^{*} Requires instructor/subject matter expert evaluation/validation.

TABLE 2. EQUIPMENT REFERENCES FOR TRAINING TASKS (continued)

				REFERENCES	
FRAINING	TASKS (EMERGENCY PROCEDURES)		PAA-1	NAVAIR 01-75PAC-6-1	MRC
	Generator reset procedure	s Sec	5-35	marine long -	
	Overvoltage reset	Sec	5-35		
	Undervoltage reset	Sec	5-35		
ext	gine failure (Item a, creme or abnormal engine oration, not required)	Sec	5-36		
•	No. 1 and No. 2 engines inoperative	Sec	5-36		
•	No. 2 and No. 3 engines inoperative	Sec	5-36A		
•	No. 3 and No. 4 engines inoperative	Sec	5-36A		
	No. 1 and No. 4 engines inoperative	Sec	5-36A		
	No. 1 and No. 3 engines inoperative	Sec	5-36A		
	No. 2 and No. 4 engines inoperative	Sec	5-37		
•	Decoupling (Good fidelity required)	Sec	5-37		
	Temperature datum system malfunction	Sec	5-38		
- Eng	gine shutdown procedure	Sec	5-38		
	ight control system Ifunctions	Sec	5-38		
•	Shifting to boost-off in flight	Sec	5-38		
•	Turning boosters on or off in flight	Sec	5-39		

TABLE 2. EQUIPMENT REFERENCES FOR TRAINING TASKS (continued)

		REFERENCES	
TRAINING TASKS (EMERGENCY PROCEDURES)	NATOPS 01-75 PAA-1	NAVAIR 01-75PAC-6-1	MRC
- Fuel system failure	Sec 5-39	107615H90 .	
 Fuel quantity indicating system failure 	Sec 5-39		
. Fuel boost pump failure	Sec 5-39		
Fuel boost pump failure in climb	Sec 5-40		
. Transfer pump failure, tank 5	Sec 5-40		
- Oil system failure (engine)	Sec 5-41		
. Magnetic chip detector indication	Sec 5-41		
. EDC failure	Sec 5-41		
- Propeller malfunctions	Sec 5-41		
. Operation without RPM indication	Sec 5-41		
Propeller pump warni	ng Sec 5-41		
. RPM fluctuation in fligh	t Sec 5-42		
. Propeller offspeed in flight	Sec 5-42	ees lagged	
. Operation with pitch- locked propeller (Good fidelity required)	Sec 5-42		
. Propeller fails-to-feath completely		eranica dipatria processora	
- Propeller malfunction during landing	Sec 5-43		
- Loss of all airspeed indicat	ion Sec 5-44		

TABLE 2. EQUIPMENT REFERENCES FOR TRAINING TASKS (continued)

		REFERENCES	
TRAINING TASKS (EMERGENCY PROCEDURES) 01	NATOPS -75 PAA-1	NAVAIR 01-75PAC-6-1	MRC
- Hydraulic power system failure	Sec 5-47	nancial de la comp	
. Failure of No. 1 & No. 2 hydraulic systems	Sec 5-47		
Landing Gear System Emergencies	Sec 5-47		
- Unsafe landing gear indication	Sec 5-47		
- Unlocked gear indication landing	Sec 5-48		

erdali lana, turalomina envaluat ete to tectori turalores

ng dawie saint it we believe to read the denotions of the second

with more comprehensive and detailed data, should they be needed. 2
INSTRUCTOR STATION REQUIREMENTS

Instructor station requirements are shown separately from the pilot, copilot, and flight engineer station requirements.

RESASWTAC school personnel request that the forward or rear instructor station have control over the following variables:

- . Emergency conditions as specified in NATOPS section 5-1, 2
- . NAVAID control capabilities specific to VOR, TACAN, ILS (no glideslope) and GCA (including controller simulation capability)
- . UHF radio (ICS and transmit monitoring and communication).

Instructor control of the following annunciator panel lights and corresponding system functions is required:

- . No. 1, 2, 3, or 4 primary fuel pump lights during start
- . No 1, 2, 3, and 4 auto feather lights
- . No. 1, 2, 3, or 4 engine starter control valve open lights
- . No. 1, 2, 3, or 4 prop feather button lights
- Fan out light
- . EDC temperature high light
- Refr. overheat light
- Left and right wing hot lights
- . No. 1, 2, 3, and 4 engine bleed air valve lights

A copy of all references annotated to show required and nonrequired OFT equipment has been forwarded with this report to appropriate NAVTRAEQUIPCEN project and engineering personnel.

- . Left and right fuselage bleed air shutoff valve lights
- . Leading edge hot light
- . EMP de-ice light
- . No. 1, 2, 3, and 4 engine anti-ice advisory light
- . Windshield heat cycling lights
- . Left and right heater out pitot heater light
- . No. 1, 2, 3, or 4 feather valve and NTS lights
- . Doors light
- . Armed light
- . No. 1, 2, 3, and 4 filter light
- . No. 1, 2, 3, and 4 pressure low light
- . No. 1, 2, 3, and 4 tank shutoff valve advisory lights
- . No. 1, 2, 3, and 4 X feed valve advisory lights
- . Cross ship X feed valve advisory light
- . Tank boost pump low pressure advisory light
- . Transfer pumps pressure low advisory light
- . Generator mechanical failure lights
- . Chips lights
- . Oil hot lights
- . Oil pressure lights
- . Prop pump No. 1 and 2 lights
- . Beta lights
- . Fuselage duct hot lights
- . Cabin pressure lights
- . Master de-icing light
- . Master electrical power light
- . Master pressure system light

- . Start valve light
- . Autopilot/RAWS warning light
- . Flap asymmetry light
- . Door open light
- . Rudder power light
- . No. 1, 1A, and 2 hydraulic pressure lights
- . No. 1, 1A, and 2 hydraulic oil hot lights
- . NTS inoperative light
- . Generator off light
- . APU generator off light
- . Transformer-rectifier overheat light
- . Propeller overspeed light
- . Propeller decoupling light
- . Engine fire light
- . Engine paralleling

The main control panel must have the following instructorcontrolled capabilities:

- . Hydraulic quantity reservice
- . Fuel/refuel
- . HRD system reservice
- . Engine oil reservice
- . Engine instrument gauge adjustment (ability to change readings)
- . T.I.T. gauge (control of engine temperature)
- . Start button (premature pop)

The functional simulation required to support the training of tasks listed in table 2 comprises all but two of the major systems and capabilities of a modern operational flight trainer. The two exceptions are the visual and motion systems. A detailed engineering evaluation should be conducted to validate this observation.

SECTION IV

REFURBISHMENT PRIORITIES AND SUPPORT PERSONNEL

REFURBISHMENT PRIORITIES

The high degree of 2F69D OFT system component interrelationships did not make it feasible to assign priorities to specific systems or subsystems on a basis of user training requirements. Most normal and emergency procedures involve numerous subsystems, each of which is critical to required and frequently-performed aircrew tasks.

"Priority" information was obtained for NAVAIDS and the motion system. NAVAIDS priorities are as follows:

- FIRST A usable GCA capability and one other landing aid (TACAN, VOR, or ILS without glidescope).
- SECOND Complete refurbishment of the present NAVAID package.
- THIRD An updated digital NAVAID package similar to that included on more modern OFTs; e.g., Device 2F87F.

Obviously, if dollar cost and implementation delays were not involved, the priorities above would be reversed.

Trainer motion was not considered to be a high priority requirement. Instructors placed motion in a "nice-to-have" versus a "required" category. This instructor attitude is supported by

other studies^{3,4} which report that use of motion increases pilot acceptance of operational flight trainers. The TAEG study also reports no major effect in simulator or aircraft performance as a function of motion in the simulator.

RESASWTAC 2F69D SUPPORT PERSONNEL

The RESASWTAC school, after analyzing overall 2F69D WST support requirements, has requested the following billets:

- . 29 TDs (22 requested and 7 existing)
- . 13 civilian technicians (existing)
- . 1 GS-11 FER (billet requested).

School personnel state that they do not anticipate problems in filling their new billets or in training new personnel. Some newly assigned TDs are already attending training courses.

Implementation of the 2F69D into the training program is very likely to be a difficult and demanding effort, especially if performed by a staff composed of TDs and technicians with limited analog and 2F69D experience. For this reason, and to prevent resulting long delays in making the device ready for training, it is recommended that NAVRES consider obtaining augmented support

Ryan, L. E., Scott, P. G., and Browning, R. F. The Effects of Simulator Landing Practice and the Contribution of Motion Simulation to P-3 Pilot Training. TAEG Report No. 63. 1978. Training Analysis and Evaluation Group, Orlando, FL.

Martin, E. L. and Waag, W. L. Contributions of Platform Motion to Simulator Training Effectiveness: Study 1 - Basic Contact. AFHRL-TR-78-15. 1978. Air Force Human Resources Laboratory, Flying Training Division, Williams Air Force Base, Arizona.

from other agencies to assist in device implementation and checkout, and to provide necessary technician training. NAVEDTRASUPPCENLANT and FASOTRAGRULANT commands should be consulted for
additional support.

Arrangements are underway to have newly assigned RESASWTAC School TDs attend a 2-week course on the 2F69D at NAS Brunswick. The course, though undoubtedly beneficial, will fall far short of providing job readiness and the provision of additional training should be strongly considered. The need for more adequate training is indicated because experienced 2F69D technicians report that existing maintenance publications do not support, or cannot be readily used by, inexperienced personnel.

SECTION V

TRAINING DEVICE ALTERNATIVES AND RECOMMENDATION TRAINING DEVICE ALTERNATIVES

Five options or alternatives are considered relative to NAVRES training requirements at NAS Willow Grove, Pennsylvania. Each alternative has advantages and disadvantages in terms of user training requirements, usability, supportability, and cost. Alternatives listed in order of increasing estimated dollar cost, with associated major considerations, are discussed below. A matrix facilitating a comparison of alternatives is shown in table 3.

- 1. Convert 2F69D to a CPT-level device. A CPT, though cheaper to maintain and use than an OFT, would fail to meet many user NATOPS check, instrument check, and instructor and transition training requirements. A CPT would support training for a significant number of emergency procedures but would be very limited and less capable for a substantial portion of realistic normal procedure training. Restricted capability would undoubtedly cause limited acceptance and training use.
- 2. Transfer the 2F69D "as is" and attempt improved maintenance/logistics support. This option would leave most existing major logistics problems untreated. The parts supply problem, which is a major cause of the existing unacceptable 2F69D maintenance and reliability status,

ALTERNATIVE MEDIA CAPABILITY AND COST FACTORS TABLE 3.

ALTERNATIVES	NATOPS CHECKS	INSTRU- MENT CHECKS	INSTRUC- TOR TRNG	ONGOING PILOT & FLT ENGR TRAINING	TRAINING IMPLEMEN- TATION DELAY	ESTIMATED INITIAL COST	ANTICIPATED RELIABILITY
CPT level	Ĝi,	(4)	<u>Gu</u>	P -	Moderate	Low	Normal
Transfer device "as is"	4	A SOLE	Second G Capana Capana	4	Very little	Low	Poor
Refurbish required existing components	le da Q DA De	6 1	e in ad ea	er end er dayses	Moderate	Moderate	Fair to normal
Refurbish required existing components and upgrade NAVAIDS and control loading capabilities	tinik sane	U	t	A from the state of the state o	Moderate	Moderate to high	Normal
Procure a 2F87F OFT	٩	υ	υ	υ	Excessive	Very high	Normal

Legend:

F indicates a failure to meet training requirements.

P indicates a partial training capability.

C indicates a complete or nearly complete training capability.

Specific initial cost and training implementation delay data will require further analysis by the NAVTRAEQUIPCEN engineering staff. NOTE:

would continue. It is very doubtful that the Naval Reserves would accept this option unless future funding for a 2F87F could be promised within the next 2 or 3 years. The option would, however, provide the quickest training capability to the user, a very important factor due to existing NAVRES training requirements.

- Overhaul/refurbish required existing components (without digital upgrade). This option, if performed in a way that would minimize existing reliability problems and restore device design capabilities, would meet most user training requirements. Unless many key components and spares were produced and made available within the supply system, the device would still be marginally reliable and would not, over an extended time period, be fully usable. The radio navigational aids capability would still be difficult to use, marginally accurate, and costly to maintain. Instrument training would undoubtedly be impaired by system availability and reliability.
- digitally upgrade the NAVAIDS capability. This option would have the same features as alternative No. 3 above but would provide for a more accurate and usable navigation capability. Reliability and maintainability of the NAVAIDS package would significantly be improved. This option would, however, be significantly more costly and may cause a longer delay than alternatives 2 or 3 in device training implementation.

5. Procure a new digital 2F87F. This option, if selected alone, though fully meeting training requirements, could cause a 2 to 5-year delay in device training implementation. Initial cost factors, however, would be relatively high in comparison to the other options. Among the advantages of a 2F87F is that the device would meet NAVRES training requirements when the RESFORONS convert from the P-3 A/B to the P-3C aircraft (which they eventually will do). During the interim, the device would be much more reliable than the 2F69D and is capable of providing training for P-3 A/B pilots. The cost effectiveness of training using the 2F87F is well documented. 5,6,7

RECOMMENDATION BASED ON TRAINING CONSIDERATIONS

Existing and planned NAVRES OFT training requirements, exclusive of unknown budget constraints, appear to justify combining the alternatives of transferring the Brunswick 2F69D to Willow Grove and initiating plans to procure a follow-on 2F87f. The 2F87F alternative alone, though meeting training capability

Browning, R. F., Ryan, L. E., Scott, P. G., and Smode, A. F. Training Effectiveness Evaluation of Device 2F87F, P-3C Operational Flight Trainer. TAEG Report No. 42. 1977. Training Analysis and Evaluation Group, Orlando, FL.

Browning, R. F., Ryan, L. E., and Scott, P. G. <u>Utilization of Device 2F87F OFT to Achieve Flight Hour Reductions in P-3 Fleet Replacement Pilot Training, TAEG Report No. 54. 1978.</u>
Training Analysis and Evaluation Group, Orlando, FL.

Op. cit. TAEG Report No. 63.

and availability requirements, would require the user to be deprived of an OFT device for several more years. Planned training utilization previously shown in table 1 presents a sound argument for providing an OFT capability at the earliest feasible date. The existing 2F69D at NAS Brunswick, though impaired by serious maintenance and logistics problems, could contribute significantly to the NAVRES program at NAS Willow Grove until a 2F87F could be procured and implemented. RESASWTAC training personnel recently "flew" the 2F69D at NAS Brunswick and reported that in its present condition the device would be exceptionally valuable to their training program.

The 2F69D at NAS Brunswick has been used heavily without major refurbishment for a period of 13 years. With well managed maintenance and logistics support, the device should be usable for several more years, but it is very doubtful that it can be feasibly maintained over the extended service life of the P-3. For this reason, it is recommended that an early effort be initiated to procure a reliable device, such as the 2F87F for follow-on training.

Selecting the option of combining both alternatives would initially impose a high maintenance burden on support personnel because the knowledge and skill level required to maintain the 2F69D in an "as is" condition would be relatively high. The alternative of transferring the Brunswick 2F69D to Willow Grove keeps the door open for other alternatives such as updating the NAVAID package and/or the control loading system. Decisions to implement these alternatives would be dependent upon the 2F87F procurement outcome and, if procured, the associated RFT date.

SECTION VI

AN IMPORTANT COST FACTOR

Decisions related to refurbishment will be based on training requirements, cost, scheduling, availability of parts and technical capabilities, and alternative solutions; i.e., other media or training methods. There is little doubt that cost will be a principal consideration. This section of the report will address one cost factor that should be considered in addition to those costs associated with procuring, modifying, or refurbishing the 2F69D or other devices.

With the effective use of an OFT, the cost savings from flight hour reductions could be sufficient to justify any training solution considered in this report. However, the achievement of a savings in flight hours is dependent upon RESASWTAC and the Reserve Squadrons setting flight hour savings as a goal. This is not likely to occur. Although the Chief of Naval Operations (CNO) authorized flight hour minimum is 100 hours/pilot/year, the Reserve feels strongly that their present flight time allowance of 120 hours/pilot/year is insufficient.

It is not the purpose or intent of this report to dispute flight hour requirements of the Naval Reserve; however, the opportunity for flight hour reductions should be addressed.

Resultant savings would offer the Reserve a powerful argument in their attempt to obtain a flight simulator.

The cost data shown in this section are not precise and should not be used for budget purposes. The data are close estimates of actual simulator and aircraft costs and are adequate for planning purposes.

Without benefit of their own flight simulator (they have limited access to others), the Naval Reserve administers an air program involving over 35,000 flight hours each year in the P-3 A/B aircraft. Since each flight hour counts as two pilot hours, 35,000 flight hours represent 70,000 pilot hours. There is no question that an OFT could contribute significantly to the Reserve program. The data shown in table 4 attest to the possible savings.

The data are based on RESASWTAC intentions to give 60 to 65 percent of the NATOPS check and the entire instrument check in Device 2F69D. RESASWTAC estimates they will provide NATOPS checks to 75 pilots/year and instrument checks to 80 pilots/year. The possible flight hour and cost savings are shown.

The data in table 4 only reflect flight hour reductions and cost savings when using the 2F69D for NATOPS and instrument checks. There is ample evidence that flight hours in other areas of the RESFORON curriculum could be reduced through use of the 2F69D. For example, one study by TAEG has shown that effective use of the 2F69D can significantly reduce the flight hours in the FRS squadrons. In that study, flight hours were reduced from 19.25 to 11.75, a 42 percent reduction. This does not suggest a reduction of that magnitude is possible, or even desired, for the Reserve program. It does show the effectiveness of training

Browning, R. F., Ryan, L. E., and Scott, P. G. Training Analysis of P-3 Replacement Pilot and Flight Engineer Training. TAEG Report No. 10. 1973. Training Analysis and Evaluation Group, Orlando, FL. AD 773745

COST SAVINGS THROUGH USE OF DEVICE 2F69D FOR NATOPS AND INSTRUMENT CHECKS TABLE 4.

Column	(1)	(2)	(3)	(4)	(2)	(9)
	Flight Hrs Saved	ight Hrs Squadron Saved Pilots	Total Hrs Saved/Yr Cols (1x2)		Total Total Operating Operating Cost/Hr* Cost/Hr** P-3 2F69D C	Total Operating Cost Cost/Hr** Savings/Year 2F69D Cols (3x4)-(3x5)
Trainer NATOPS Check	2.0	75	150	1,412	100	196,800
Trainer Instrument Check	ck 2.0	80	160	1,412	100	209,920
					TOTAL	\$406,720

costs include petroleum, oil, lube, maintenance, replenishment spares, aircraft reworks O&M, aircraft OPS O&M, and SDLM O&M. Military salaries have been excluded from these Total operating * From Navy Program Factors Manual OPNAV 90P-02B, revised 31 Aug 1978. cost estimates.

P-3A total operating cost \$1,412/flt hr. P-3B total operating cost \$1,413/flt hr. Average cost \$1,412/flt hr (rounded to nearest dollar)

be \$115.43; no cost is shown for the 2F69D OFT. The operating cost of the 2F69D OFT is assumed to be slightly less than that of the 2F87F OFT since the 2F69D has no visual system. In this report the operating cost of the 2F69D OFT is estimated to be \$100/hr. Military personnel salaries From POM 79, U.S. Navy, U.S. Naval Reserve, U.S. Marine Corps OSD/OMB budget for simulator and training device programs. The POM shows the hourly operating cost The operating costs include costs such as spares, electricity, heat, water, and The 2F87F OFT is shown to maintenance. Field engineer salaries are also included. for the 2F87 WST and the 2F69D WST to be \$313.20. and MILCON are not included.

using the device. Although the mission and training goals of the Reserve and FRS are different, in many respects the curricula are identical.

Figure 1 shows cost savings possible through a reduction in RESFORON flight hours. The total cost for operating the 2F69D OFT 4,627¹⁰ hours annually is also shown. Cost savings associated with flight hour reductions are calculated as follows:

Pilots in RESFORON X flight hour reductions X P-3 A/B operating cost/hour = annual cost savings.


 $585 \times 1 \times 1,412 = $826,020$ $585 \times 2 \times 1,412 = $1,652,040$

 $585 \times 3 \times 1,412 = $2,478,060$

As shown in figure 1, the "breakeven point"; i.e., the point at which flight hour savings offset the operating cost of the simulator, occurs at less than 1 hour/pilot/year. The exact number is .56 flight hours reduction/pilot/year required for the Reserve to offset the total cost of operating Device 2F69D OFT. This small reduction in flight hours could be accomplished with either Device 2F69D or Device 2F87F.

A reduction of .56 flight hours would not violate CNO regulations and would be in line with DOD "policy" to reduce flight hours. At this time, regulations authorize the substitution of 50 hours in the OFT for 50 hours in the P-3 A/B in meeting the CNO minimum requirements of 100 hours/pilot/year.

¹⁰ RESASWTAC estimate.



*Based on RESASWTAC estimate (4,267 hrs x \$100/hr).

Figure 1. Cost Savings vs. Flight Hour Reduction

However, for annual qualification purposes, pilots need 45 hours in the aircraft every 6 months (90 hours/year). Thus, the Reserve could choose to reduce flight hours from 120 to 90/pilot/year.

The authors of this report do not make any recommendations relative to flight hour reduction. The above data are presented to support the justification of an OFT for the Naval Reserve air program on the basis of cost savings through minimal flight hour reductions, should such a consideration be required.

APPENDIX A

PATROL SQUADRON/UNIT SYLLABUS FOR OFT 1, 2, 3, AND 4

This appendix is a copy of the OFT syllabus from the Patrol Squadron/Unit Training Manual (CNAVRESINST 3500.2A).

COMP BATTERY START
USE OF GROUND AIR AND GROUND POWER FOR START
ENGINE START (NORWAL)
AFTER START CHECKLIST
TAXI (DISCUSS PROCEDURES, BRAKE FEEL AND USE, POWER LEVEL USE, NO BETA LIGHT ON LANDING
FLIGHT IDLE STOP OVERRIDE
AFTER LANDING CHECKLIST
FUEL GOVERNOR/PITCHLOCK/REVERSE HORSEPOWER CHECK
SECURE CHECKLIST ANTI-ICE/DE-ICE SYSTEMS CHECKS AND MALFUNCTIONS
TAKE-OFF CHECKLIST
RADIO SET-UPS
TAKE-OFF BRIEF
TAKE-OFF
CLIMB CHECKLIST
NTS CHECK GOVERNOR INDEXING
NORMAL CLIMB
TRANSITION TO CRUISE
AIR CONDITIONING AND PRESSURIZATION SYSTEM USE
DESCENT CHECKLIST
NORMAL DESCENT PILOT P3 A/B OFT 1 (DUAL RESPONSE) TASK BEFORE START CHECKLIST START BRIEF LANDING CHECKLIST NORMAL LANDING RPM SHIFT) 401.1230 401.127 1 401.128 401.26 401.27 NA 401.28 401.120 401.121 401.320 401.122 POS REF 401.19 401.21 NA

		INSTRUCTOR SIGNATURE	OPT HOURS
	INCOMPLETE		
COMMENTS:	COMPLETE	PILOT NAME:	DATE:

MA	PQS REF	TASK	COMP
START BRIEF START BRIEF START START START CHECKLIST (1.120 TAKE-OFF CHECKLIST (1.121 TAKE-OFF CHECKLIST (1.122 TAKE-OFF CHECKLIST (1.123 TAKE-OFF CHECKLIST (1.124 CLIMB CHECKLIST (1.124 CLIMB CHECKLIST (1.125 TAKE-OFF PROCEDURES (1.126 ON TONALL TAKE-OFF PROCEDURES (1.127 TAKE-OFF PROCEDURES (1.127 USE OF AUTO FEATHER (1.128 ON TONALL TAKE-OFF PROCEDURES (1.129 TAKE-OFF PROCEDURES (1.120 TAKE-OFF PROCEDURES (1.121 TAKE-OFF PROCEDURES (1.121 TAKE-OFF PROCEDURES (1.132 TAKE-OFF PROCEDURES (1.133 LOW HYDRAULIC FLUID QUANTITY (1.134 TAKE-OFF PROCEDURE (1.135 TAKE-OFF PROCEDURES (1.136 TAKE-OFF PROCEDURES (1.137 TAKE-OFF PROCEDURES (1.137 TAKE-OFF PROCEDURES (1.138 LOW HYDRAULIC FLUID QUANTITY (1.130 TAKE-OFF PROCEDURES (1.131 TAKE-OFF PROCEDURES (1.132 TAKE-OFF PROCEDURES (1.133 TAKE-OFF PROCEDURES (1.134 TAKE-OFF PROCEDURES (1.135 TAKE-OFF PROCEDURES (1.136 TAKE-OFF PROCEDURES (1.137 TAKE-OFF PROCEDURES (1.138 TAKE-OFF PROCEDURES (1.139 TAKE-OFF PROCEDURES (1.130 TAKE-OFF PROCEDURES (1.131 TAKE-OFF PROCEDURES (1.132 TAKE-OFF PROCEDURES (1.133 TAKE-OFF PROCEDURES (1.134 TAKE-OFF PROCEDURES (1.135 TAKE-OFF PROCEDURES (1.136 TAKE-OFF PROCEDURES (1.137 TAKE-OFF PROCEDURES (1.138 TAKE-OFF PROCEDURES (1.139 TAKE-OFF PROCEDURES (1.130 TAKE-OFF PROCEDURES (1.130 TAKE-OFF PROCEDURES (1.131 TAKE-OFF PROCEDURES (1.132 TAKE-OFF PROCEDURES (1.133 TAKE-OFF PROCEDURES (1.134 TAKE-OFF PROCEDURE (1.135 TAKE-OFF PROCEDURE (1.136 TAKE-OFF PROCEDURE (1.137 TAKE-OFF PROCEDURE (1.138 TAKE-OFF PROCEDURE (1.139 TAKE-OFF PROCEDURE (1.130 TAKE-OFF PROCEDURE (1.130 TAKE-OFF PROCEDURE (1.130 TAKE-OFF PROCEDURE (1.134 TAKE-OFF PROCEDURE (1.135 TAKE-OFF PROCEDURE (1.135 TAKE-OFF PROCEDURE (1.136 TAKE-OFF PROCEDURE (1.137 TAKE-OFF PROCEDURE (1.138 TAKE-OFF PROCEDURE (1.139 TAKE-OFF PROCEDURE (1.130 TAKE-OFF PROCEDURE (1.130 TAKE-OFF PROCEDURE (1.130 TAKE-OFF PROCEDURE (1.131 TAKE-OFF PROCEDURE (1.134 TAKE-OFF PROCEDURE (1.135 TAKE-OFF PROCEDURE (1.135 TAKE-OFF PROCEDURE	401.19	BEFORE START CHECKLIST	
STAGNATED START STAGNATED START STALLED START 1.12 ENGINE FIRE ON GROUND 1.120 AFTER START CHECKLIST 1.121 TAKE—OFF CHECKLIST 1.123 NORMAL TAKE—OFF PROCEDURES 1.123 NORMAL TAKE—OFF PROCEDURES 1.124 CLIDIA CHECKLIST AND PROCEDURES 1.125 FUEL MANGEMENT/TRANSFER/CROSSFEED 1.136 FUEL BOOST PUMP FAILURE 1.131 UNGARE GEAR INDICATIONS 1.131 UNGARE GEAR INDICATIONS 1.131 UNGARE GEAR INDICATIONS 1.132 MANGER MALEVENCENCISS 1.133 LOW ENGINE OIL TEMP 1.134 LANDING GEAR EMERCENCIS 1.135 FUEL SHP, TIT, F/F 1.136 ENGINE FAILURE IN FLIGHT (NORMAL) 1.137 ELUX SHP, TIT, F/F 1.138 LANDING GEARLIST 1.139 LOW ENGINE OIL PRESCUE 1.130 SECURE CHECKLIST 1.131 SECURE CHECKLIST 1.132 SECURE CHECKLIST 1.133 SECURE CHECKLIST 1.134 SECURE CHECKLIST 1.135 SECURE CHECKLIST 1.136 SECURE CHECKLIST 1.137 SECURE CHECKLIST 1.138 SECURE CHECKLIST 1.139 SECURE CHECKLIST 1.130 SECURE CHECKLIST 1.130 SECURE CHECKLIST 1.131 SECURE CHECKLIST 1.132 SECURE CHECKLIST 1.134 SECURE CHECKLIST 1.135 SECURE CHECKLIST 1.136 SECURE CHECKLIST 1.137 SECURE CHECKLIST 1.138 SECURE CHECKLIST 1.139 SECURE CHECKLIST 1.130 SECURE CHE	NA	START BRIEF	
STALLED START 1.120 AFTER START CHECKLIST 1.121 TAKE-OFF CHECKLIST 1.123 NARE-OFF CHECKLIST 1.124 CLIMB CHECKLIST 1.124 CLIMB CHECKLIST AND PROCEDURES 1.125 NORMAL TAKE-OFF PROCEDURES 1.125 NORMAL TAKE-OFF PROCEDURES 1.126 CLIMB CHECKLIST AND PROCEDURES 1.127 CLIMB CHECKLIST AND PROCEDURES 1.28 NORMAL TAKE-OFF PROCEDURES 1.29 NORMAL TAKE-OFF PROCEDURES 1.21 ENG DAIVEN CENTRIFUGAL BOOST PUMP FAILURE 1.22 LOW ENGINE OIL PRESSURE 1.23 LOW ENGINE OIL PRESSURE 1.24 ENGINE PAILURE IN FLIGHT (DEMO SHUTDOWN, DISCUSS "E" 1.25 LANDLING CHECKLIST 1.26 LANDLING CHECKLIST 1.27 BESCHAT CHECKLIST 1.28 LANDLING CHECKLIST 1.29 ENGURE CHECKLIST 1.20 SECURE CHECKLIST 1.20 SECURE CHECKLIST 1.21 BRAKE FIREHOT BRAKE 1.22 SECURE CHECKLIST 1.23 COMPLETE 1.24 INCOMPLETE 1.25 COMPLETE 1.26 CANDLING CHECKLIST 1.27 DESCENT CHECKLIST 1.28 COMPLETE 1.39 COMPLETE 1.40 SHORT SIGNATURE 1.41 SHAME PIREFHOT BRAKE 1.42 SECURE CHECKLIST 1.43 SECURE CHECKLIST 1.44 SHAME PIREFHOT BRAKE 1.45 SECURE CHECKLIST 1.55 COMPLETE 1.55	NA	STAGNATED START	
1.120 AFTER START CHECKLIST 1.121 AFTER START CHECKLIST 1.123 USE OF AUTO FEATHER 1.123 USE OF AUTO FEATHER 1.123 NORMAL TAKE-OFF PROCEDURES 1.124 NTS CHECK 1.125 NTS CHECK 1.125 NTS CHECK 1.125 FUEL MANAGEMENT/TRANSFER/CROSSFEED 1.126 FUEL MANAGEMENT/TRANSFER/CROSSFEED 1.27 FUEL MANAGEMENT/TRANSFER/CROSSFEED 1.28 ENG PUMP FAILURE 1.29 UNSAFE GEAR INDICATIONS 1.31 LOW HYDRAULIC SYSTEM FAILURE (DISCUSS LANDING W/O #1 SYS 1.31 LOW HYDRAULIC SYSTEM FAILURE (DISCUSS LANDING W/O #1 SYS 1.31 LOW BUGINE OIL TEMP 1.32 LOW ENGINE OIL TEMP 1.33 LOW ENGINE OIL TEMP 1.34 LOW ENGINE OIL TEMP 1.35 FULL SHP, TIT, F/F 1.36 MAGNET IC CHIP DETECTOR INDICATION 1.37 LOW ENGINE OIL QUANTITY 1.38 LOW ENGINE OIL QUANTITY 1.39 LOW ENGINE OIL DETECTOR INDICATION 1.30 LOW ENGINE OIL DETECTOR INDICATION 1.31 ELUX SHP, TIT, F/F 1.32 ELUX SHP, TIT, F/F 1.34 LANDING GHECKLIST 1.35 SECURE CHECKLIST 1.36 SECURE CHECKLIST 1.37 DESCURE CHECKLIST 1.38 LANDING GHECKLIST 1.39 SECURE CHECKLIST 1.30 SECURE CHECKLIST 1.31 COMPLETE	NA	STALLED START	
1.120 AFTE-DEF START CHECKLIST 1.123 NORMAL TAKE-OFF PROCEDURES 1.123 NORMAL TAKE-OFF PROCEDURES 1.124 CLIMB CHECKLIST AND PROCEDURES 1.125 NUS CHECK 1.25 NUS CHECK 1.26 FUEL MANAGEMENT/TRANSFER/CROSSFEED 1.316 TRANSFER PUMF FAILURE 1.316 TRANSFER PUMF FAILURE 1.317 NUS CHECK 1.318 HYDRAULIC FLUID QUANTITY 1.319 UNSAFE GEAR INDICATIONS 1.310 UNSAFE GEAR INDICATIONS 1.311 HYDRAULIC FLUID QUANTITY 1.312 ILANDINE PILLURE IN FLIGHT (NORMAL) 1.313 LOW ENGINE OIL TEMP 1.314 MAGNET IC CHIP DETECTOR INDICATION 1.315 LANDINE PALLURE IN FLIGHT (NORMAL) 1.317 "E" HANDLE VIBRATION 1.317 "E" HANDLE VIBRATION 1.317 "E" HANDLE VIBRATION 1.317 "ELGINE FLICHT (DEWO SHUTDOWN, DISCUSS "E" 1.318 LANDING CHECKLIST 1.319 SECURE CHECKLIST 1.319 SECURE CHECKLIST 1.310 SECURE CHECKLIST 1.311 COMPLETE	401.42	ENGINE FIRE ON GROUND	
1.122 TAKE-OFF CHECKLIST 1.123 NORMAL TAKE-OFF PROCEDURES 1.124 CLIMB CHECKLIST AND PROCEDURES 1.125 NTS CRECK 1.125 NTS CRECK 1.25 FUEL MANAGEMENT/TRANSFER/CROSSFEED 1.35 FUEL BOOST PUMP FAILURE 1.316 TRANSFER PUMP FAILURE 1.317 FUEL DUMP 1.318 LOW HYDRAULIC FLUID QUANTITY 1.319 UNSAFER GEAR INDICATIONS 1.319 UNSAFE GEAR FALERGENCIES 1.319 LOW ENGINE OIL TEMP 1.32 LOW ENGINE OIL TEMP 1.33 LOW ENGINE OIL PETECTOR INDICATION 1.34 LOW ENGINE OIL QUANTITY 1.35 LOW ENGINE OIL PETECTOR INDICATION 1.37 FLUX SHP TIT, FF 1.38 LANDLE VIBRATION 1.39 LOW ENGINE FALLURE IN FLIGHT (DEMO SHUTDOWN, DISCUSS "E" 1.30 ELOX SHP TIT, FF 1.31 BRAKE FIRE/HOT BRAKE 1.32 LANDING CHECKLIST 1.34 BRAKE FIRE/HOT BRAKE 1.35 LANDING CHECKLIST 1.36 SECURE CHECKLIST 1.39 SECURE CHECKLIST 1.30 SECURE CHECKLIST 1.40 SECURE CHECKLIST 1.	401.120	AFIER START CHECKLIST	
USE OF AUTO FEATHER 1.123 NORMAL TAKE-OFF PROCEDURES 1.124 NTS CHECK 1.125 NTS CHECK 1.126 NTS CHECK 1.127 NTS CHECK 1.127 FUEL MANAGEMENT/TRANSFER/CROSSFEED 1.28 FUEL BOOST PUMP FAILURE 1.29 TEALSFER PUMP FAILURE 1.29 TEALSFER PUMP FAILURE 1.20 ENGINE PUMP FAILURE 1.318 HYDRAULG SYSTEM FAILURE 1.319 UNSAFE GEAR INDICATIONS 1.319 UNSAFE GEAR INDICATIONS 1.31 HIGH ENGINE OIL PRESSURE 1.32 LOW ENGINE OIL PRESSURE 1.33 LOW ENGINE OIL PRESSURE 1.34 LOW ENGINE OIL PRESSURE 1.35 LOW ENGINE OIL PRESSURE 1.37 "E" HANDLE VIBRATION 1.37 "E" HANDLE VIBRATION 1.37 "E" HANDLE VIBRATION 1.37 "E" HANDLE VIBRATION 1.38 LANDING CHECKLIST 1.39 LANDING CHECKLIST 1.31 BRAKE PIRE/HOT BRAKE 1.31 SECURE CHECKLIST MENTS: 1.32 LANDING CHECKLIST 1.33 SECURE CHECKLIST 1.34 SECURE CHECKLIST 1.35 PULL SHE 1.36 SECURE CHECKLIST 1.37 PERSONE CHECKLIST 1.38 PURPLE PRESSURE 1.39 LANDING CHECKLIST 1.30 SECURE CHECKLIST 1.31 SECURE CHECKLIST 1.32 PULL SHE 1.33 SECURE CHECKLIST 1.34 SARE PIRE/HOT BRAKE 1.35 PULL SHE 1.36 SECURE CHECKLIST 1.37 PERSONE CHECKLIST 1.38 PURPLE CHECKLIST 1.39 PURPLE CHECKLIST 1.30 PURPLE CHECKLIST 1.31 PURPLE CHECKLIST 1.32 PURPLE CHECKLIST 1.34 PURPLE CHECKLIST 1.35 PULL SHE 1.35 PULL SHE 1.35 PULL SHE 1.36 PURPLE CHECKLIST 1.37 PURPLE CHECKLIST 1.38 PURPLE CHECKLIST 1.39 PURPLE CHECKLIST 1.30 PURPLE CHECKLIST 1.31 PURPLE CHECKLIST 1.31 PURPLE CHECKLIST 1.32 PURPLE CHECKLIST 1.34 PURPLE CHECKLIST 1.35 PULL SHE 1.36 PURPLE CHECKLIST 1.37 PURPLE CHECKLIST 1.38 PURPLE CHECKLIST 1.39 PURPLE CHECKLIST 1.30 PURPLE CHECKLIST 1.30 PURPLE CHECKLIST 1.31 PURPLE CHECKLIST 1.31 PURPLE CHECKLIST 1.32 PURPLE CHECKLIST 1.34 PURPLE CHECKLIST 1.55 PURPLE CHECKLIST 1.55 PURPLE CHECKLIST 1.56 PURPLE CHECKLIST 1.57 PURPLE CHECKLIST 1.58 PURPLE CHECKLIST 1.58 PURPLE CHECKLIST 1.59 PURPLE CHECKLIST 1.50	401.122	TAKE-OFF CHECKLIST	
1.1234 NORMAL TAKE-OFF PROCEDURES 1.124 NITIAB CHECKLIST AND PROCEDURES 1.25 NITIAB CHECKLIST AND PROCEDURES 1.26 FUEL MANAGEMENT/TRANSFER/CROSSFEED 1.35 FUEL BOOST PUMP FAILURE 1.31 FUEL DUMP 1.31 B LOW HYDRAULIC FIUID QUANTITY 1.31 B LANDING GEAR INDICATIONS 1.31 HYDRAULIC SYSTEM FAILURE (DISCUSS LANDING W/O #1 SYS 1.31 HYDRAULIC SYSTEM FAILURE 1.33 LOW HYDRAULIC SYSTEM FAILURE 1.34 LOW HYDRAULIC SYSTEM FAILURE 1.35 LOW HYDRAULIC SYSTEM FAILURE 1.36 LANDING GEAR EMERGENIES 1.37 LOW ENGINE OIL PRESSURE 1.34 LOW ENGINE OIL PRESSURE 1.35 LOW ENGINE OIL QUANTITY 1.37 ENGINE FAILURE IN FLIGHT (NORMAL) 1.37 ELUX SHP, TIT, F/F 1.37 ENGINE RESTART DURING FLIGHT (NORMAL) 1.38 LANDING CHECKLIST 1.39 SECURE CHECKLIST 1.30 SECURE CHECKLIST AMENTS: COMPLETE	NA		
1.124 CLIMB CHECKLIST AND PROCEDURES 1.25 FUEL MANGEMENT/TRANSFER/CROSSFEED 1.35 FUEL MANGEMENT/TRANSFER/CROSSFEED 1.31 FUEL DOORT PUMP FAILURE 1.31 TRANSFER PUMP FAILURE 1.31 LOW HYDRAULIC FLUID QUANTITY 1.31 HYDRAULIC SYSTEM FAILURE (DISCUSS LANDING W/O #1 SYS 1.319 UNSAFE GEAR INDICATIONS 1.31 HYDRAULIC SYSTEM FAILURE (DISCUSS LANDING W/O #1 SYS 1.31 HYDRAULIC SYSTEM FAILURE 1.32 HYDRAULIC SYSTEM FAILURE 1.33 HIGH ENGINE OIL TEMP 1.34 LOW ENGINE OIL TEMP 1.35 LOW ENGINE OIL TEMP 1.37 "E" HANDLE VIBRATION 1.37 "E" HANDLE VIBRATION 1.37 "E" HANDLE VIBRATION 1.37 "E" HANDLE VIBRATION 1.37 ENGINE FESTIVE DIN FLIGHT (DEMO SHUTDOWN, DISCUSS "E" 1.34 ENGINE RESTALRY DURING FLIGHT (NORMAL) 1.35 ENGINE RESTALRY 1.36 ENGINE RESTALRY 1.37 BECURE CHECKLIST 1.38 SECURE CHECKLIST 1.39 SECURE CHECKLIST 1.30 SECURE CHECKLIST 1.310 SECURE CHECKLIST 1.310 SECURE CHECKLIST 1.3110 SECURE CHECKLIST 1.3110 SECURE CHECKLIST 1.3120 SECURE CHECKLIST 1.3130 SECURE CHECKLIST 1.3130 SECURE CHECKLIST 1.3140 SECURE CHECKLIST 1.3150 SECURE CHECKLIST 1.5150 SECURE CHECKLIST	401.123a	NORMAL TAKE-OFF	
1.22 NTS CHECK 1.316 FUEL MANAGEMENT/TRANSFER/CROSSFEED 1.316 TRANSFER PUMP FAILURE 1.316 TRANSFER PUMP FAILURE 1.317 FUEL DUMP 1.318 HYDRAULIC FLUID QUANTITY 1.318 HYDRAULIC FLUID QUANTITY 1.319 UNSAFE GEAR INDICATIONS 1.310 LOW ENGINE OIL PRESSURE 1.310 LOW ENGINE OIL PRESSURE 1.3110 ENGINE FOLD EUGHATITY 1.3110 ENGINE FOLD EUGHATION 1.312 RUNN SHP, TIT, F/F 1.313 ELUX SHP, TIT, F/F 1.314 ENGINE RESTALURE IN FLIGHT (NORMAL) 1.315 ELUX SHP, TIT, F/F 1.316 ENGINE RESTALURE 1.317 DESCENT CHECKLIST 1.318 ISRAKE FIRE/HOT BRAKE 1.319 ISRAKE FIRE/HOT BRAKE 1.310 ISRUER CHECKLIST 1.3110 ISRUER CHECKLIST 1	401.124	CLIMB CHECKLIST	
FUEL MANAGEMENT/TRANSFER/CROSSFEED 1.35	401.22	NTS CHECK	
1.35 FUEL BOOST PUMP FAILURE 1.51 FUEL BOOST PUMP FAILURE 1.51 ENG DAVID 1.51 LANDING GEAR INDICATIONS 1.31 LOW ENGINE OIL TEMP 1.32 LOW ENGINE OIL TEMP 1.34 LOW ENGINE OIL TEMP 1.35 LOW ENGINE OIL TEMP 1.36 LOW ENGINE OIL TEMP 1.37 "E" HANDLE VIBRATION 1.38 LOW ENGINE ENSTART DURING FLIGHT (NORMAL) 1.39 ELUX SHP, TIT, F/F 1.40 ENGINE RESTART DURING FLIGHT (NORMAL) 1.41 BRAKE FIRE/HOT BRAKE 1.41 BRAKE FIRE/HOT BRAKE 1.41 BRAKE FIRE/HOT BRAKE 1.41 BRAKE FIRE/HOT BRAKE 1.42 ENGINE CHECKLIST 1.44 BRAKE FIRE/HOT BRAKE 1.45 ENGINE CHECKLIST 1.46 ENGINE CHECKLIST 1.47 ENGINE CHECKLIST 1.48 LANDING CHECKLIST 1.49 ENGINE CHECKLIST 1.40 ENGINE CHECKLIST 1.41 BRAKE FIRE/HOT BRAKE 1.42 ENGINE CHECKLIST 1.44 BRAKE FIRE/HOT BRAKE 1.45 ENGINE CHECKLIST 1.55 LANDING CHECKLIST 1.56 LANDING CHECKLIST 1.57 ENGINE CHECKLIST 1.58 LANDING CHECKLIST 1.59 ECURE CHECKLIST 1.50 SECURE CHECKL	NA	FUEL MANAGEMENT/TRANSFER/CROSSFEED	
1.51 FUEL DUMP FAILURE 1.51 FUEL DUMP FAILURE 1.51 ENG DAUNE 1.38 LOW HYDRAULIC FLUID QUANTITY 1.319 UNSAFE GEAR INDICATIONS 1.319 UNSAFE GEAR INDICATIONS 1.319 UNSAFE GEAR EMERGENCIES 1.319 UNSAFE GEAR EMERGENCIES 1.310 LANDING GEAR EMERGENCIES 1.310 LANDING GEAR EMERGENCIES 1.310 LANDING OIL PRESSURE 1.310 LOW ENGINE OIL PRESSURE 1.311 LANDILE VIBRATION 1.311 LANDILE VIBRATION 1.312 ELUX SHP, TIT, F/F 1.311 LANDILE VIBRATION 1.312 FLUX SHP, TIT, F/F 1.311 LANDING CHECKLIST 1.310 SECURE CHECKLIST 1.311 SECURE CHECKLIST 1.311 COMPLETE 1.312 LANDING CHECKLIST 1.312 LANDING CHECKLIST 1.313 SECURE CHECKLIST 1.314 LANDING CHECKLIST 1.315 SECURE CHECKLIST 1.315 SECURE CHECKLIST 1.316 SECURE CHECKLIST 1.317 LANDING CHECKLIST 1.318 LANDING CHECKLIST 1.319 SECURE CHECKLIST 1.310 SECURE CHECKLIST 1.310 SECURE CHECKLIST 1.311	401.35	FUEL BOOST PUMP FAILURE	
ENG DIVER 1.318 HYDRAULIC SYSTEM FAILURE 1.318 HYDRAULIC SYSTEM FAILURE (DISCUSS LANDING W/O #1 SYS 1.319 UNSAFE GEAR INDICATIONS 1.319 UNSAFE GEAR INDICATIONS 1.31 HIGH ENGINE OIL TEMP 1.31 HOW ENGINE OIL TEMP 1.31 HOW ENGINE OIL QUANTITY 1.32 LOW ENGINE OIL QUANTITY 1.31 LOW ENGINE OIL QUANTITY 1.32 FLUX SHP, TIT, F/F 1.31 RAGNET IC CHIP DETECTOR INDICATION 1.32 FLUX SHP, TIT, F/F 1.34 ENGINE FAILURE IN FLIGHT (NORMAL) 1.35 FLUX SHP, TIT, F/F 1.36 ENGINE RESTART DURING FLIGHT (NORMAL) 1.37 TEMBORIC CHECKLIST 1.39 LOW ENGINE CHECKLIST 1.30 SECURE CHECKLIST 1.30 SECURE CHECKLIST 1.30 SECURE CHECKLIST 1.31 COMPLETE INCOMPLETE 1.32 INSTRUCTOR SIGNATURE 1.34 COMPLETE INCOMPLETE 1.35 COMPLETE INCOMPLETE 1.36 SECURE CHECKLIST 1.37 SECURE CHECKLIST 1.38 SECURE CHECKLIST 1.39 SECURE CHECKLIST 1.30 SECURE CHECKLIST 1.30 SECURE CHECKLIST 1.31 SECURE CHECKLIST 1.32 SECURE CHECKLIST 1.34 SECURE CHECKLIST 1.35 SECURE CHECKLIST 1.45 SECURE CHECKLIST 1.55 SECURE CHECKLIST 1.56 SECURE CHECKLIST 1.57 SECURE CHECKLIST 1.58 SECURE CHECKLIST 1.50 SECURE CHECKLIST 1	401.316	TRANSFER PUMP FAILURE	
1.38 LOW HYDRAULIC SYSTEM FAILURE (DISCUSS LANDING W/O \$1 SYS. 1.318 HYDRAULIC SYSTEM FAILURE (DISCUSS LANDING W/O \$1 SYS. 1.319 UNSAFE GEAR INDICATIONS 1.31 LOW ENGINE OIL PRESSURE 1.32 LOW ENGINE OIL PRESSURE 1.33 LOW ENGINE OIL QUANTITY 1.31 LOW ENGINE OIL QUANTITY 1.32 LOW ENGINE OIL QUANTITY 1.31 PE HANDLE VIERTON 1.32 FLUX SHP, TIT, F/F 1.31 FE HANDLE PAILURE IN FLIGHT (NORMAL) 1.24 ENGINE FAILURE IN FLIGHT (NORMAL) 1.25 LANDING CHECKLIST 1.26 LANDING CHECKLIST 1.27 DESCENT CHECKLIST 1.30 SECURE CHECKLIST 1.30 SECURE CHECKLIST 1.31 COMPLETE INCOMPLETE COMPLETE INCOMPLETE OFT HAND: OFT HAND: OFT HANDLE OFT HOURS	401.51		
HYDRAULIC SYSTEM FAILURE (DISCUSS LANDING W/O #1 SYS UNSAFE GEAR INDICATIONS LANDING GEAR EMERGENCIES BOOST PACKAGE MALFUNCTIONS HIGH ENGINE OIL PRESSURE LOW ENGINE OIL PRESSURE LOW ENGINE OIL PRESSURE LOW ENGINE OIL PRESSURE LOW ENGINE OIL PRESCURE WAGNET IC CHIP DETECTOR INDICATION "E" HANDLE VIBRATION FLUX SHP, TIT, F/F ENGINE FAILURE IN FLIGHT (NORMAL) DESCENT CHECKLIST ENGINE RESTART DURING FLIGHT (NORMAL) DESCENT CHECKLIST SECURE CHECKLIST SECURE CHECKLIST SECURE CHECKLIST SECURE CHECKLIST SECURE CHECKLIST SHAME: INSTRUCTOR SIGNATURE AME:	401.38	1.	
UNSAFE GEAR INDICATIONS LANDING GEAR EMERGENCIES BOOST PACKAGE MALEUNCTIONS HIGH ENGINE OIL TEMP LOW ENGINE OIL PRESSURE LOW ENGINE OIL PRESSURE LOW ENGINE OIL PRESSURE LOW ENGINE OIL PRESCURE LOW ENGINE OIL QUANTITY MAGNET IC CHIP DETECTOR INDICATION "E" HANDLE VIBRATION FLUX SHP, TIT, F/F ENGINE FAILURE IN FLIGHT (NORMAL) DESCENT CHECKLIST ENGINE RESTART DURING FLIGHT (NORMAL) LANDING CHECKLIST BRAKE FIRE/HOT BRAKE SECURE CHECKLIST SECURE CHECKLIST COMPLETE INCOMPLETE INSTRUCTOR SIGNATURE AME: COMPLETE COMP	401.318	SCUSS LANDING W/O #1	
LANDING GEAR EMERGENCIES BOOST PACKAGE MALFUNCTIONS HIGH ENGINE OIL TEMP LOW ENGINE OIL TEMP LOW ENGINE OIL PRESSURE LOW ENGINE OIL QUANTITY MAGNET IC CHIP DETECTOR INDICATION "E" HANDLE VIBRATION FLUN SHP, TIT, F/F ENGINE RESTALINE IN FLIGHT (NORMAL) DESCENT CHECKLIST LANDING CHECKLIST SECURE CHECKLIST SECURE CHECKLIST SECURE CHECKLIST AME: INSTRUCTOR SIGNATURE INSTRUCTOR SIGNATURE	401.319		
HIGH ENGINE OIL TEMP LOW ENGINE OIL TEMP LOW ENGINE OIL PRESSURE LOW ENGINE OIL PRESSURE LOW ENGINE OIL QUANTITY MAGNET IC CHIP DETECTOR INDICATION "E" HANDLE VIBRATION "E" HANDLE VIBRATION "E" HANDLE VIBRATION FLUX SHP, TIT, F/F ENGINE RESTART DIVING FLIGHT (NORMAL) DESCENT CHECKLIST LANDING CHECKLIST SECURE CHECKLIST SECURE CHECKLIST SECURE CHECKLIST SHAKE FIRE/HOT BRAKE SECURE CHECKLIST AME: INSTRUCTOR SIGNATURE	401.418	LANDING GEAR EMERGENCIES	
HIGH ENGINE OIL TEMP LOW ENGINE OIL PRESSURE LOW ENGINE OIL QUANTITY MAGNET IC CHIP DETECTOR INDICATION "E" HANDLE VIBRATION FLUX SHP, TIT, F/F ENGINE RESTART IN FLIGHT (DEMO SHUTDOWN, DISCUSS "E" ENGINE RESTART DURING FLIGHT (NORMAL) DESCENT CHECKLIST LANDING CHECKLIST SECURE CHECKLIST SECURE CHECKLIST SECURE CHECKLIST SHAKE INCOMPLETE INSTRUCTOR SIGNATURE OFF HOURS	401.410	BOOST PACKAGE MALFUNCTIONS	
LOW ENGINE OIL PRESSURE LOW ENGINE OIL QUANTITY MAGNET IC CHIP DETECTOR INDICATION "E" HANDLE VIBRATION "E" HANDLE VIBRATION "E" HANDLE VIBRATION "ENGINE FESTART DURING FLIGHT (NORMAL) DESCENT CHECKLIST LANDING CHECKLIST BRAKE FIRE/HOT BRAKE SECURE CHECKLIST SECURE CHECKLIST SHAME: INSTRUCTOR SIGNATURE OFF HOIDS	401.33	HIGH ENGINE OIL TEMP	
LOW ENGINE OIL QUANTITY MAGNET IC CHIP DETECTOR INDICATION "E" HANDLE VIBRATION FLUX SHP, TIT, F/F ENGINE FAILURE IN FLIGHT (DEMO SHUTDOWN, DISCUSS "E" ENGINE RESTART DURING FLIGHT (NORMAL) DESCENT CHECKLIST LANDING CHECKLIST SECURE CHECKLIST SECURE CHECKLIST SECURE CHECKLIST SHAKE INCOMPLETE INSTRUCTOR SIGNATURE OFF HOURS	401.34	LOW ENGINE OIL PRESSURE	
MAGNET IC CHIP DETECTOR INDICATION "E" HANDLE VIBRATION "E" HANDLE VIBRATION FLUX SHP, TIT, F/F ENGINE FAILURE IN FLIGHT (DEMO SHUTDOWN, DISCUSS "E" ENGINE RESTART DURING FLIGHT (NORMAL) DESCENT CHECKLIST LANDING CHECKLIST BRAKE FIRE/HOT BRAKE SECURE CHECKLIST SECURE CHECKLIST COMPLETE INCOMPLETE INSTRUCTOR SIGNATURE OFF HOIDS	401.39	LOW ENGINE OIL QUANTITY	
FLUX SHP, TIT, F/F FLUX SHP, TIT, F/F ENGINE FAILURE IN FLIGHT (DEMO SHUTDOWN, DISCUSS "E" ENGINE RESTART DURING FLIGHT (NORMAL) DESCENT CHECKLIST LANDING CHECKLIST SECURE CHECKLIST SECURE CHECKLIST SECURE CHECKLIST COMPLETE INCOMPLETE INSTRUCTOR SIGNATURE OFF HOURS	401.412	MAGNET IC CHIP DETECTOR INDICATION	
ENGINE FAILURE IN FLIGHT (DEMO SHUTDOWN, DISCUSS "E" ENGINE RESTART DURING FLIGHT (NORMAL) DESCENT CHECKLIST LANDING CHECKLIST BRAKE FIRE/HOT BRAKE SECURE CHECKLIST COMPLETE INCOMPLETE INSTRUCTOR SIGNATURE OF HOTES	401.37	E HANDLE VIBRATION	
BRAKE FIRE/HOT BRAKE SECURE CHECKLIST SECURE CHECKLIST SECURE CHECKLIST SHOUNG CHECKLIST BRAKE FIRE/HOT BRAKE SECURE CHECKLIST COMPLETE INSTRUCTOR SIGNATURE OFF HOIDS	401.32	TN DITCHE (PENC CHEMPONE SECOND FOR	
DESCENT CHECKLIST LANDING CHECKLIST BRAKE FIRE/HOT BRAKE SECURE CHECKLIST SECURE CHECKLIST SECURE CHECKLIST SAME:	401 24	THE FLIGHT (DEMO SHUTDOWN, DISCUSS "E"	
S: COMPLETE	401 157	PROCESS CHECKILED FLIGHT (NORMAL)	
S: COMPLETE	401.128	LANDING CHECKLIST	
S: COMPLETE INCOMPLETE	401.41	BRAKE FIRE/HOT BRAKE	
MPLETE [] INCOMPLETE	401.130	SECURE CHECKLIST	
LETE INCOMPLETE	COMMENTS		
LETE INCOMPLETE			
		ם	
	PILOT NA		
	DATE:	Sallya may	

401.19 B NA NA S	TASK	CONTO
61.1		
66	BEFORE START CHECKLIST	
130		-
H	START MALFUNCTION (OVERTEMP T/D PROTECTION)	
	AFTER START CHECKLIST	
2	TAKE-OFF CHECKLIST	
401.43 N	MALFUNCTION PRIOR TO VR (4 ENG ABORT)	-
	TAKE-OFF PROCEDURES	
4	CLIMB CHECKLIST AND PROCEDURES	
-	NTS CHECK	
4	TEMP DATUM SYSTEM CHECK AND MALFUNCTION	
	TIT OVERTEMP	
H	DITCHING DRILL PROCEDURES	-
	RPM FLUX	-
-	PROP OFFSPEED IN-FLIGHT	
Н	TACH GEN FAILURE	
	PROP OVERSPEED IN-FLIGHT WITH AND W/O PROP PUMP LIGHTS	
_	PROP FAILS TO FEATHER	
	PROP PUMP WARNING LIGHTS	
9	PITCHLOCK PROP	
401.24 E	ENGINE RESTART IN-FLIGHT (NORMAL, BLADE ANGLE NO ROTATION,	
-	NO OIL PRESSURE	
	FUSELAGE/ELECTRICAL FIRE OF UNKNOWN ORIGIN	
0	SMOKE AND FUME ELIMINATION	
+	EMERGENCY DESCENT PROCEDURES	
1.58	EMERGENCY DEPRESSURIZATION	
-	AIR CONDITIONING AND PRESSURIZATION SYSTEM	
_	DESCENT CHECKLIST	
_	LANDING CHECKLIST	
401.129 A	AFTER LANDING CHECKLIST	
	FUEL GOVERNOR PITCHLOCK/REV HP CHECK	-
6	SECURE CHECKLIST	
COMMENTS:		
COMPLETE	PLETE INCOMPLETE	
PILOT NAME:	:: INSTRUCTOR SIGNATURE:	
	Californ many	
DATE:	OFT HOOKS:	

	COMP																																				
PILOT P3 A/B OFT 4	TASK	BEFORE START CHECKLIST		NCTION	ENGINE FIRE		RUNAROUND RE	TAKE-OFF CHE	MALFUNCTION PRIOR TO VR	MALFUNCTION AFTER VR (OVERSPEED)	NTS CHECK		T	٦	FAILURE OF PROP TO FEATHER	_	THREE ENGINE LOITER	LENGINE RESIDENT INFLIGHT (NIS-INOF)	REP PETAVE	1014	TRANSFORMER RECTIFIER FAILURES	GENERATOR FAILURE	t	APU INFLIGHT OPERATION/LOAD MONITORING/SINGLE GENERATOR OPERATION	RESTORING ELECTRICAL POWER	CRACKED WINDSHIELD					AFTER LANDING CHECKLIST	П	55:		COMPLETE INCOMPLETE	INSTRUCTOR SIGNATURE	OFT HOURS
	POS REF	401.19	NA	NA	401.42	401.120	NA	401.122	401.43	401.44	401.22	NA	401.311	401.31	401.414	401.140	401.1236	401.140	*07.70		402.48		401.46	NA	NA	401.31	401.59	401.127	401.128	401.310	401.129	401.130	COMMENTS			PILOT NAME:	DATE:

APPENDIX B

PATROL SQUADRON/UNIT SYLLABUS FOR OFT 5

This appendix is a copy of the OFT syllabus from the Patrol Squadron/Unit Training Manual (CNAVRESINST 3500.2A).

23 AUG 1974

NAT	POS REF	COMP
ALL CHECKLISTS COMPLETED IN ACCORDANCE WITH NATOPS STATEMY CANAET DISCUSSION BANTERY START ENGINE FIRE ON THE GROUND HALFUNCTIONS PATER REFUSAL ELECTRICLE BALE ON THE GROUND HALFUNCTIONS PATER REFUSAL ELECTRICLE BALE OF PEATHER ENGINE FILED ENGINE FILE ON THE GROUND HALFUNCTIONS AFTER REFUSAL ENGINE FAILURE IN FILENT ENGINE CHARLE OF PEATHER ENGINE OIL TEMPERATURE ALMUDING GEAR EMERSIUME ALMUDING GEAR EMERSIUME ALMUDING GEAR ENGINE ELUCYUATION REM ELUCTUATION REM ELUCYUATION REM HIGH ENGINE OIL TEMPERATURE AND HEIGHE DATUM SYSTEM MALFUNCTION ENGINE OIL TEMPERATURE AND HEIGHE DATUM SYSTEM MALFUNCTION EVEL TRANSFER PUMP FAILURE FUEL TRANSFER PUMP FAILURE EVEL TRANSFER PUMP FAILURE EVER GROUND FAILURE EVEL TRANSFER PUMP FAILURE EVER FAYOR SAILURE EVER FAYOR SAILURE	COCKETT BERETICUM	
ANTERNATION STATEM STATEM ANCORDANCE MITH NATURES B ANTERNATION COMPLETED IN ACCORDANCE MITH NATURES B ANTERNATION STATEM STATEM BALCHNICTIONS PAINOR TO REFUSAL ENGINE PALLEN ON AFTER REFUSAL ELECTRICAL BUS FAILURE ENGINE PALLEN OF REPRESED PROPELLER PAILS TO FEATHER PROPELLER PAILS FAILURE LOW ENGINE DIL PRESSURE LOW ENGINE DIL PRESSURE LOW ENGINE DIL PRESSURE LOW ENGINE DIL PRESSURE LOW ENGINE DATURE LAURE DATURE LOW ENGINE DATURE PROPERTY PAILURE PROPERTY PAILUR	1	
BANTERY STARY BANTERY ON THE GROUND HALFUNCTIONS AFTER REFUSAL ELECTRICAL BUS FAILURE BASS OF PICLET BOST PACKAGE PROPELLER FAILS TO FEATHER BANTERY SERVENCES LAND ING GRAR BENESTRICATION BENESTRY OF STREET LOW BYDAULIC FULD QUANTITY COMPENSATION RAW FULL BOOST PUMP FAILURE BYDRAULIC SYSTEM FAILURE THENERATOR FAILURE BYDRAULIC SYSTEM FAILURE TACH GENERATOR FAILURE BYDRAULIC SYSTEM FAILURE TACH GENERATOR FAILURE BYDRAULIC SYSTEM FAILURE TACH GENERATOR FAILURE TACH GENERATOR FAILURE BYDRAULIC SYSTEM FAILURE TACH GENERATOR FAILURE TACH GENERATOR FAILURE BYDRAULIC SYSTEM FAILURE TACH GENERATOR FAILURE TACH GENERATOR FAILURE BYDRAULIC SYSTEM FAILURE TACH GENERATOR FAILURE TACH GENERATOR FAILURE TACH GENERATOR FAILURE BYDRAULIC SYSTEM FAILURE TACH GENERATOR FAILURE TACH GENERATOR FAILURE TACH GENERATOR FAILURE THORETAL LIGHT ON LANDING ONE BYDALL HOURS TACH GENERATOR FAILURE TACH GENERATOR FAILURE		TOPS
REGINE THE OF THE GROUND MALENUATIONS PRIOR TO REFUSAL RALEURICAL BUS PRIOR TO REFUSAL RALEURICAL BUS PAILURE REGINE PALLINE RACIGUR PALLURE IN FLIGHT LOSS OF FLICHT BOOST PACKAGE PROPELLER VERSEBEL PROPELLER PALLS TO FRATHER PROPELLER PALLS TO TIT, AND FULL FLOW HIGH BUGING OIL PRESSURE LOW BAGINE DATUR SYSTEM MALFUNCTION FUNCTIONING REALURE ROW BAGINE DATUR SYSTEM MALFUNCTION FULL BOOST PUMP FALUNE ROST PUMP FALUNE PROPELLER OFFSPERD FULL RAMSER DATUR SYSTEM MALFUNCTION FULL BOOST PUMP PRESS LOW LIGHT TACH GENERATOR FALUNE PROPELLER OFFSPERD FULL RAMSER PUMP FALUNE FULL RAMSER PALUNE FULL RAMSER PARTER PALUNE FULL RAMSER PARTER PALUNE FULL RAMSER PARTER PARTER PALUNE FULL RAMSER PARTER P	212	
MALPUNCTIONS PRIOR THE GROUD MALPUNCTIONS PRIOR THE GROUD EMCITIONS PRIOR THE GROUD ELECTRICAL BUS FAILURE ENGINE FALLURE IN FLIGHT LOSS OF FIGHT BOOST PACKAGE PROPELLER PAILS TO PEATHER PROPELLER OVERSPEED LOW ENGINE DIT TEMPERATION HIGH ENGINE DIT TEMPERATURE LOW ENGINE DIT PRESSURE LOW ENGINE DATUN SYSTEM MALFUNCTION PROPELLER OFFICE PRILURE PROPELLER CENTRIFUEDAL PROPELLER OFFICE PRILURE PROPERT OFFICE PROPERTY PROPERTY OFFICE PROPERT	21.	
MALEUNCTIONS AFTER REUSAL MALEUNCTIONS AFTER REUSAL RALLEUNCTIONS AFTER REUSAL ELECTRICAL BUS PALLURE ENGINE FAILURE ENGINE PAILURE ENGINE TAILS TO PEATHER PROPELLER WARNING LIGHTS PROPELLER WARNING LIGHTS EMERGENCY DEPRESSURE PROPELLER WARNING LIGHTS EMERGENCY DEPRESSURE PROPELLER WARNING LIGHTS EMERGENCY DEPRESSURE ILANDIATION RPM FLUCTUATION FLUCTUATION RPM FLUCTUATION FLUCTUATION FLUCTUATION FLUCTUATION FROM ENGINE OIL TEMPERATURE LOW BYDRAULIC FLUID QUANTITY CARCKED WINDSHIELD FROM ENGINE OIL GENERATORE FROM ENGINE OIL FROM ENGINE FROM ENGINE OIL FROM ENGINE FROM ENGINE OIL FROM ENGINE FROM ENGINE	+	
ELECTRICAL BUS FAILURE ENGINE PAILURE IN FLIGHT LOSS OF FLIGHT LOSS OF FLIGHT ENGINE PAILURE IN FLIGHT LOSS OF FLIGHT ENGINE PAILURE IN FLIGHT ENGINE PAILURE IN FLIGHT FROPELLER FAILURE LANDRING GEAR EMERGENCIES EMERGENCY DEPRESSURIZATION EMERGENCY DEPRESSURIZATION EMERGENCY DEPRESSURE LOW ENGINE OIL TEMPERATURE LOW ENGINE OIL PRESSURE HOT BRAKE LOW ENGINE OIL PRESSURE THE LEANOR FAILURE FUEL TRANSFER PUMP FAILURE FUEL TRANSFER LANDING ON BETA LIGHT ON LANDING ON THOUSE INSTRUCTOR SIGNATURE INSTRUCTOR SIGNATURE AME: ON THOUSE	+	
ELECTRIAL BY PALIURE ENGINE PALLUE ENGINE PALLUE LOSS OF FILGET LOSS OF FILGET LOSS OF FILGET PROPELLER VASHESPEED PROPELLER VASHESPEED PROPELLER PALICS TO FEATHER PROPELLER PALICS OF EATHER EMERGENCY DEPRESSURIZATION FLUCTUATION RPM FLUCTUATION FLUCTUATION RPM FLUCTUATION F	+	
HOUSE PAILURE IN FLIGHT LOSS OF FLIGHT BOOST PACKAGE PROPELLER OVERSPEED PROPELLER FALLS TO FRATER PROPELLER FALLS TO FRATER PROPELLER FALLS FALLS LANDING GEAR EMERGENCIES LANDING GEAR EMERGENCIES EMERGENCY DERESSURITION FLUCTUATION RPM FLUCTUAT		
LOSS OF PLICHT BOOST PACKAGE PROPELLER PLICHT BOOST PACKAGE PROPELLER PLICHT FALLS TO FEATHER PROPELLER PALLS TO FEATHER PROPELLER PALLS TO FEATHER PROPELLER PALLS TO FEATHER PROPELLER PALLS TO FEATHOR EMERGENCY BARKE OPERATION FLUCTUATION RAM FULL BROAD RAM FULL BROST PUMP FAILURE PROPELLER OFFSPEED PROPERTOR OFFSPEED PROPELLER OFFSPEED PROPELLER OFFSPEED PROPERTOR OFFSPEED PROPERTOR OFFSPEED PROPERTOR OFFSPEED PR		
PROPELLER OVERSPEED PROPELLER NATURE TO FEATHER PROPELLER PAILS TO FEATHER PROPELLER MARNING LIGHTS LANDING GRAR EMEGRACIES EMERGENCY BRAKE OPERATION EMERGENCY BRAKE OPERATION EMERGENCY BRAKE OPERATION FLUCTUATION SHP FLUCTUATION SHP FLUCTUATION SHP HIGH ENGINE OIL TEMPERATURE LOW ENGINE OIL QUANTITY CORCLED OFFSPEED PROPELLER OFFSPEED PROPELLE OFFSPEED PROPELLER OFFSPEED PROPELLER OFFSPEED PROPELLER OFFSPE		
PROPELLER PALIS TO FRATHER	-	
PROPELLER WANNING LIGHTS LANDING GEAR EMERGENCIES EMERGENCY BRAKE OPERATION FLUCTUATION RPM FLUCTUATION RPM FLUCTUATION RPM FLUCTUATION RPM TIT, AND FULL FLOW HIGH ENGINE OIL TEMPERATURE LOW ENGINE OIL TEMPERATURE LOW ENGINE OIL PRESSURE HOW ENGINE OIL TEMPERATURE LOW ENGINE OIL PRESSURE HOW ENGINE OIL TEMPERATURE LOW ENGINE OIL TEMPERATURE LOW ENGINE OIL QUANTITY CRACKED WINDSHIELD PROPELLER OFFSPEED FULL PRANSFER PUPP FAILURE FULL BOOST PUMP PRESS LOW LIGHT PROPELLER OFFSPEED FULL TRANSFER PUPP FAILURE FULL PRANSFER PUPP FAILURE FULL TRANSFER PUPP FAILURE TACH GENERATOR FAILURE PROPELLER OFFSPEED TACH GENERATOR FAILURE TACH GENERATOR FAILURE TACH GENERATOR FAILURE PROPELLE AND ING CEAR INDICATION TASK OWNER LANDING CEAR INDICATION IND BETA LIGHT ON LANDING IND BETA LIGHT ON LANDING COMPLETE INSTRUCTOR SIGNATURE AME: OFT HOURS		
LANDING GEAR EMERGENCIES EMERGENCY DEPRESSURIZATION EMERGENCY DEPRESSURIZATION FLUCTUATION RAM FURE LOOP RAM FURE BOOST PUMP PRESS LOW LIGHT FURE BOOST PUMP PRESS LOW LIGHT FURE BOOST PUMP PRESS LOW LIGHT FURE TANNSFER PUMP FAILURE BYDRAULIC SYSTEM FAILURE FURE TANNSFER PUMP	H	
EMERGENCY DEPRESSURIZATION EMERGENCY DEPRESSURIZATION FLUCTUATION RPM TOWN ENGINE OIL TEMPERATURE LOW ENGINE OIL QUANTITY LOW ENGINE OIL QUANTITY LOW ENGINE OIL QUANTITY COMPLIER ONFESTED GENERATOR FAILURE FULL LOWERATURE DATUM SYSTEM MALFUNCTION FULL TRANSFER PUMP FAILURE FULL BOOST PUMP FAILURE FULL TRANSFER PUMP FAILURE FULL	┢	
EMERGENCY BRAKE OPERATION FLUCTUATION RPM FLUCTUATION RPM FLUCTUATION RPM HIGH ENGINE OIL TEMPERATURE LOW ENGINE OIL TEMPERATURE LOW ENGINE OIL TEMPERATURE LOW BY BY BAIL OR HOT BRAKE HOT BRAKE HOT BRAKE TIT OVERTEMPERATURE HOT BRAKE ROILE OUNTITY CAM ENGINE OIL QUANTITY CAM ENGINE OIL QUANTITY CRACKED WINDSHIELD PROPELLER OFFSPED REMEMATOR FAILURE FUEL BOOST PUMP FAILURE FUEL BOOST PUM	+	
FILUCTUATION RPM HIGH ENGINE OIL TEMPERATURE LOW ENGINE OIL QUANTITY LOW ENGINE OIL QUANTITY LOW HYDRAULIC FLUID QUANTITY CRACKED WINDSHIELD PROPELLER OFFSPEED RENERATURE DATUM SYSTEM MALFUNCTION PROPELLER OFFSPEED RENERATURE DATUM FAILURE FUEL TRANSFER PUMP FAILURE FUEL TRANSFER PUMP FAILURE FUEL TRANSFER PUMP FAILURE FUEL TRANSFER PUMP FAILURE TACH GENERATOR EAILURE HYDRAULIC SYSTEM FAILURE TACH GENERATOR FAILURE FUEL TRANSFER LANDING GEAR INDICATION IN O BETA LIGHT ON LANDING COMPLETE TACH RENERATURE TASH RENERATOR FAILURE FULL TRANSFER PUMP FRESS LOW LIGHT FACIL GENERATOR FAILURE FULL TASK RAGINE TASK ONSTRUCTOR SIGNATURE TASK ONSTRUCTOR SIGNATURE TASK ONSTRUCTOR SIGNATURE TASK ONPLETE TASK ONSTRUCTOR SIGNATURE TASK ONSTRUCTOR SIGNATURE TASK ONPLETE TASK ONSTRUCTOR SIGNATURE TASK ONSTRUCTOR SIGNATURE TASK	╁	
FLUCTUATING SHP, TIT, AND FULL FLOW HIGH ENGINE OIL TEMPERATURE LOW ENGINE OIL TEMPERATURE LOW ENGINE OIL TEMPERATURE LOW ENGINE OIL TEMPERATURE LOW HYDRAULIC FLUID QUANTITY LOW HYDRAULIC FLUID QUANTITY LOW HYDRAULIC FLUID QUANTITY CRACKED WINDSHIELD CRACKED WINDSHIELD GENERATOR FAILURE TEMPERATURE DATUM SYSTEM MALFUNCTION FULL BOOST PUMP FAILURE TEMPERATURE DATUM SYSTEM MALFUNCTION FULL TRANSFER PUMP FAILURE TEMPERATURE CENTERFUGAL BOOST PUMP PRESS LOW LIGHT TACH GENERATOR FAILURE TASK COMPLETE [INCOMPLETE] INCOMPLETE [INCOMPLETE] TASK COMPLETE [INCOMPLETE] INSTRUCTOR SIGNATURE TAKE: OFT HOURS	1	
HIGH ENGINE OIL TEMPERATURE LOW ENGINE OIL TEMPERATURE LOW ENGINE OIL PRESSURE TIT ONERTEMPERATURE LOW HYDRAULIC FLUID QUANTITY LOW HYDRAULIC FLUID QUANTITY LOW HYDRAULIC FLUID QUANTITY CRACKED WINDSHLED GRACKED WINDSHLED FUEL TRANSFER PUMP FAILURE FILOT P3 A/B PPC OFT 5 (CONTINUED) GRACKED GRACKED GRACKED GRACKED GRACKED GRACKED FUEL TRANSFER PUMP FAILURE FILOT P3 A/B PPC OFT 5 (CONTINUED) GRACKED GRACKED GRACKED FUEL TRANSFER LANDING FUEL TRANSFER LANDING FILOT P3 A/B PPC OFT 5 (CONTINUED) GRACKED GRACKED		
LOW ENGINE OIL TEMPERATURE LOW ENGINE OIL TEMPERATURE LOW ENGINE OIL PRESSURE TIT OVERTEMPERATURE HOT BRAKE LOW HYDRAULIC FLUID QUANTITY LOW ENGINE OIL QUANTITY LOW ENGINE OIL QUANTITY LOW ENGINE OIL QUANTITY LOW ENGINE OIL QUANTITY CRACKED WINDEHLELD PROPELLER OFFSPEED GENERATOR FAILURE FUEL BOOST PUMP FAILURE FUEL TRANSFER PUMP FAILURE FUEL TRANSFER PUMP FAILURE TACH GENERATOR FAILURE HYDRAULIC SYSTEM FAILURE PILOT P3 A/B PPC OFT 5 (CONTINUED) HYDRAULIC SYSTEM FAILURE NO BETA LIGHT ON LANDING NO BETA LIGHT ON LANDING STACK COMPLETE INCOMPLETE INSTRUCTOR SIGNATURE		
TIT OVERFEWPERATURE HOT BRAKE HOT BRAKE HOT BRAKE LOW HYDRAULIC FLUID QUANTITY LOW HYDRAULIC FLUID QUANTITY LOW HYDRAULIC FLUID QUANTITY LOW HYDRAULIC FLUID QUANTITY CRACKED WINDSHIELD PROPELLER GENERATOR FAILURE FUEL BOOST PUMP FRESS LOW LIGHT FACH GENERATOR FAILURE FUEL BOOST PUMP FRESS LOW LIGHT FUEL BOOST PUMP FRESS LOW LIGHT FUEL BOOST PUMP FRESS LOW LIGHT FUEL BOOST PUMP FAILURE FUEL BOOST PUMP FRESS LOW LIGHT FUEL BOOST PUMP FAILURE FUEL BOOST		
TIT OVERTEMPERATURE HOT BRAKE LOW HYDRAULIC FLUID QUANTITY LOW ENGINE OIL QUANTITY LOW ENGINE OIL QUANTITY CRACKED WINDSHIELD PROPELLER OFFSPEED GENERATOR FAILURE FUEL TRANSFER PUMP F	T	
HOT BRAKE LOW HYDRAULIC FLUID QUANTITY LOW HYDRAULIC FLUID QUANTITY CRACKED WINDSHIED PROPELLER OFFSPEED GENERATOR FAILURE TEMPERATURE DATUM SYSTEM MALFUNCTION FUEL DATUM FAILURE FUEL TRANSFER PUMP FAILURE TACH GENERATOR FAILURE PILOT P3 A/B PPC OFT 5 (CONTINUED) TACH GENERATOR FAILURE PILOT P3 A/B PPC OFT 5 (CONTINUED) TACH GENERATOR FAILURE TASK TACH GENERATOR FAILURE PILOT P3 A/B PPC OFT 5 (CONTINUED) TASK	TIT OVERTEN	
LOW HYDRAULIC FLUID QUANTITY LOW ENGINE OIL QUANTITY CRACKED WINDSHIELD CRACKED WINDSHIELD CRACKED WINDSHIELD GENERATOR FAILURE TEMPERATURE DATUM SYSTEM MALFUNCTION FUEL TRANSFER PUMP FAILURE FUEL BOOST PUMP FAILURE FUEL BOOST PUMP FAILURE FUEL TRANSFER PUMP FAILURE FUEL BOOST PUMP FAILURE FUEL TRANSFER PUMP FAILURE TACH GENERATOR FAILURE PILOT P3 A/B PPC OFT 5 (CONTINUED) COMPLETE INCOMPLETE INCOMPLETE INSTRUCTOR SIGNATURE INSTRUCTOR SIGNATURE OFT HOURS	HOT	
10 CRACKED WINDSHIELD 31 CRACKED WINDSHIELD 311 CRACKED WINDSHIELD 312 GENERATOR FAILURE 313 TEMPERATURE DATUM SYSTEM MALFUNCTION 314 FUEL TRANSFER PUMP FAILURE 315 FUEL TRANSFER PUMP FAILURE 316 FUEL TRANSFER PUMP FAILURE 317 ENGINE DRIVEN CENTRIFUGAL BOOST PUMP PRESS LOW LIGHT 318 TACH GENERATOR FAILURE 319 HYDRAULIC SYSTEM FAILURE 319 HYDRAULIC SYSTEM FAILURE 320 UNSAFE LANDING GEAR INDICATION 321 NO BETA LIGHT ON LANDING 321 NO BETA LIGHT ON LANDING 322 COMPLETE INCOMPLETE 333 INSTRUCTOR SIGNATURE 334 INAME: 345 COMPLETE OF THE OF	H	
310 CRACKED WINDSHIELD 311 PROPELLER OFFSPEED 312 GENERATOR FAILURE 313 TEMPERATURE DATUM SYSTEM MALFUNCTION 313 TEMPERATURE DATUM PALLURE 314 FUEL TRANSFER PUMP FAILURE 315 FUEL TRANSFER PUMP FAILURE 316 FUEL TRANSFER PUMP FAILURE 317 ENGINE DRIVEN CENTRIFUGAL BOOST PUMP PRESS LOW LIGHT 318 TACH GENERATOR FAILURE 319 HYDRAULIC SYSTEM FAILURE 310 UNSAFE LANDING GEAR INDICATION 320 UNSAFE LANDING GEAR INDICATION 321 NO BETA LIGHT ON LANDING 321 NO BETA LIGHT ON LANDING 322 INSTRUCTOR SIGNATURE 333 INSTRUCTOR SIGNATURE 34 INAME: 35 OFF HOURS	39	
311 PROPELLER OFFSPEED 312 GENERATOR FAILURE 313 TEMPERATURE DATUM SYSTEM MALFUNCTION 314 TEMPERATURE DATUM SYSTEM MALFUNCTION 315 FUEL TRANSFER PUMP FAILURE 316 FUEL TRANSFER PUMP FAILURE 317 ENGINE DRIVEN CENTRIFUGAL BOOST PUMP PRESS LOW LIGHT 318 TACH GENERATOR FAILURE 319 HYDRAULIC SYSTEM FAILURE 310 UNSAFE LANDING GEAR INDICATION 320 UNSAFE LANDING GEAR INDICATION 321 NO BETA LIGHT ON LANDING 521 NO BETA LIGHT ON LANDING 521 TO MAKE: 532 OMPLETE STOOMPLETE 533 OFT HOURS 534 OFT HOURS		
312 GENERATOR FAILURE 313 TEMPERATURE DATUM SYSTEM MALFUNCTION 315 FUEL BOOST PUMP FAILURE 316 FUEL TRANSFER PUMP FAILURE 317 ENGINE DRIVEN CENTRIFUGAL BOOST PUMP PRESS LOW LIGHT 318 TACH GENERATOR FAILURE 319 HYDRAULIC SYSTEM FAILURE 310 UNSAFE LANDING GEAR INDICATION 321 NO BETA LIGHT ON LANDING 321 INCOMPLETE INCOMPLETE TASK TASK 322 UNSAFE LANDING GEAR INDICATION 321 INCOMPLETE OFT HOURS INSTRUCTOR SIGNATURE OFT HOURS	H	
313 TEMPERATURE DATUM SYSTEM MALFUNCTION 315 FUEL BOOST PUMP FAILURE 316 FUEL TRANSFER PUMP FAILURE 317 ENGINE DRIVEN CENTRIFUGAL BOOST PUMP PRESS LOW LIGHT 318 TACH GENERATOR FAILURE 319 HYDRAULIC SYSTEM FAILURE 310 UNSAFE LANDING GEAR INDICATION 321 NO BETA LIGHT ON LANDING 321 NO BETA LIGHT ON LANDING 322 COMPLETE INCOMPLETE T NAME: OFT HOURS OFTHORS	-	
115 FUEL BOOST PUMP FAILURE 316 FUEL TRANSFER PUMP FAILURE 317 ENGINE DRIVEN CENTRIFUGAL BOOST PUMP PRESS LOW LIGHT 318 TACH GENERATOR FAILURE 319 HYDRAULIC SYSTEM FAILURE 320 UNSAFE LANDING GEAR INDICATION 321 NO BETA LIGHT ON LANDING ENTS: TOMPLETE INCOMPLETE INSTRUCTOR SIGNATURE OFT HOURS	-	
110 FUEL TRANSFER PUMP FAILURE 317 ENGINE DRIVEN CENTRIFUGAL BOOST PUMP PRESS LOW LIGHT 318 TACH GENERATOR FAILURE 319 HYDRAULIC SYSTEM FAILURE PILOT P3 A/B PPC OFT 5 (CONTINUED) TASK 320 UNSAFE LANDING GEAR INDICATION 321 NO BETA LIGHT ON LANDING ENTS: INSTRUCTOR SIGNATURE OFT HOURS OFT HOURS	FUEL	
11 ENGINE DRIVEN CENTRIFUGAL BOOST PUMP PRESS LOW LIGHT 318 TACH GENERATOR FAILURE 319 HYDRAULIC SYSTEM FAILURE PILOT P3 A/B PPC OFT 5 (CONTINUED) TASK 320 UNSAFE LANDING GEAR INDICATION 321 NO BETA LIGHT ON LANDING ENTS: TOMPLETE INCOMPLETE INSTRUCTOR SIGNATURE OFT HOURS	1	
PILOT P3 A/B PPC OFT 5 (CONTINUED) PEF PILOT P3 A/B PPC OFT 5 (CONTINUED) TASK 320 UNSAFE LANDING GEAR INDICATION 321 NO BETA LIGHT ON LANDING ENTS: COMPLETE INCOMPLETE INSTRUCTOR SIGNATURE OFT HOURS	317	LIGHT
TASK SAFE LANDING GEAR INDICATION BETA LIGHT ON LANDING INSTRUCTOR SIGNATURE OFT HOURS	310	
TASK SAFE LANDING GEAR INDICATION BETA LIGHT ON LANDING LETE INCOMPLETE INSTRUCTOR SIGNATURE OFT HOURS		
TASK SAFE LANDING GEAR INDICATION BETA LIGHT ON LANDING LETE	P3 A/B PPC OFT 5	NTINUED)
SAFE LANDING GEAR INDICATION BETA LIGHT ON LANDING LETE		ŏ
BETA LIGHT ON LANDING LETE INCOMPLETE	+	
LETE [] INCOMPLETE	-	
LETE INCOMPLETE	COMMENTS	
LETE INCOMPLETE		
		ATURE

APPENDIX C

PATROL SQUADRON/UNIT SYLLABUS FOR IUT OFT 1

This appendix is a copy of the OFT syllabus from the Patrol Squadron/Unit Training Manual (CNAVRESINST 3500.2A).

NAVTRAEQUIPCEN TN-60 CNAVRESINST 3500.2A

2 3 AUG 1974

INSTRUCTOR PILOT SYLLABUS

IUT-OFT 1 (IUT IN RIGHT SEAT)		
1 Name of the Market	SAT	UNSAT
1. Annuciator lights		
2. APU operations/malfunctions 3. Battery start		
4. Start procedures/malfunctions		
5. Fuel governor, pitchlock reverse		
horsepower check		
6. Takeoff procedures		
7. Eng/prop malfunctions before and after VR		
8. NTS check		A STATE OF
9. Prop indexing	28033	- Albana - A
10. Electrical system/malfunction review		
11. Hydraulic system/malfunction review		
12. Prop system/malfunction review		
13. Fuel system/malfunction review		
 Anti/deicing system/malfunction review 		
Airconditioning/pressurization system/		
malfunction review		
PROSPECTIVE INSTRUCTOR:		
INSTRUCTOR PILOT:		
DATE: PILOT TIME: FLIG	HT TI	ME:
FLIGHT WAS: SAT UNSAT INCOMP	LETE	
REASON:		
REMARKS ON REVERSE		

IUT-OFT-1

unverancotuciu es-60

DISTRIBUTION LIST

Novel Training Dynipsent Center ... Orlando, Florida 32819

Cense Documentation Center 12 Common Station Maxandria, Virginia 22314